



BKIOZYB

report date: 2024-03-28

General information

Make	FORD
Model	FIESTA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	34
Total items failed	6

MOT #162023-05-19 10:44

MOT test number879803231854

Result✓ Passed

Next expiry date2024-05-22

- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Rear Coil spring corroded Nearside and Offside (5.3.1 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge- On the limit (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play On the limit (5.3.4 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #15**

2023-05-18 12:06

**MOT test number**

951056697518

**Result****✗ Failed****Advice** Nearside Front Lower Suspension arm ball joint has slight play On the limit (5.3.4 (a) (i))**Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Offside Play in steering rack inner joint(s)**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure On outer sidewall (5.2.3 (d) (ii))**Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))**Advice** Rear Coil spring corroded Nearside and Offside (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge- On the limit (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14**

2022-05-23 11:14

**MOT test number**

197471920826

**Result****✓ Passed****Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #13**

2022-05-21 10:21

**MOT test number**

715419878705

**Result****✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2021-01-18 10:25**MOT test number** 913505218914**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-01-18 10:25**MOT test number** 255848273633**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #10** 2020-01-28 14:40**MOT test number** 732152673651**Result** ✓ Passed**MOT #9** 2019-02-18 15:44**MOT test number** 839235243636**Result** ✓ Passed**Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))**MOT #8** 2018-01-08 13:52**MOT test number** 346156875168**Result** ✓ Passed**MOT #7** 2017-01-16 17:34**MOT test number** 470544374314**Result** ✓ Passed

**MOT #6** 2017-01-16 12:22**MOT test number** 275598004516**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Obligatory mirror insecure (8.1.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2016-01-19 16:38**MOT test number** 610153426680**Result** ✓ Passed**Advice** Slight fluctuation rear brakes**MOT #4** 2015-05-11 12:25**MOT test number** 156561135197**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-05-11 12:25**MOT test number** 648311035140**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-05-08 10:02
MOT test number	608158924139
Result	✓ Passed
Notice	Nearside front tyre outer sidewall slight damage

MOT #1	2013-03-19 12:08
MOT test number	568548073071
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
22 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	22 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2023-05-19
Complete history	<a href="#">See info</a>



Registration #1	2010-03-31	11 mi
Registration #2	2013-03-19	34.879 mi
Registration #3	2014-05-08	47.806 mi
Registration #4	2015-05-11	57.880 mi
Registration #5	2016-01-19	63.656 mi
Registration #6	2017-01-16	66.137 mi
Registration #7	2017-01-16	66.139 mi
Registration #8	2018-01-08	67.968 mi
Registration #9	2019-02-18	70.953 mi
Registration #10	2019-05-20	71.277 mi
Registration #11	2019-05-20	71.277 mi
Registration #12	2019-05-20	71.277 mi
Registration #13	2019-05-20	71.277 mi
Registration #14	2019-05-20	71.277 mi
Registration #15	2019-05-20	71.277 mi
Registration #16	2019-05-20	71.277 mi
Registration #17	2019-05-20	71.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1109 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	9E46444
---------------	---------