






report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 DCI ACENTA
Colour	White
Year of manufacture	2014
Top speed	98 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-27


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-12
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	14
Total items failed	11

MOT #14	2024-02-13 09:36
MOT test number	844355766246
Result	✓ Passed
Next expiry date	2025-02-12
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2023-01-25 14:12
MOT test number	460077217811
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2023-01-24 11:45 931715741488 **MOT** test number Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Windscreen wiper blade defective (3.4 (b) (i)) Fail Rear Service brake grabbing severely (1.2.1 (c)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Windscreen wiper blade defective (3.4 (b) (i)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #11

MOT test number

S81444215181

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Pass with rectification

Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

 MOT #9
 2021-06-07 08:24

 MOT test number
 741317442779

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8 2021-06-07 08:24

MOT test number 118432425356

Result X Failed

Pass with rectification Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #7 2020-06-11 13:30

MOT test number 208361397700

Result

Passed

Advice Nearside Non obligatory mirror damaged insecure

MOT #6 2020-06-11 08:35

MOT test number 472770887565

Result X Failed

Fail Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Non obligatory mirror damaged insecure

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #5 2019-04-05 10:31

MOT test number 291390853257

Result

✓ Passed

MOT #4 2019-03-29 09:30

MOT test number 570063318825

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Fail Offside Front Outer Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3 2018-04-04 15:38

MOT test number 347705693110

MOT #2 2018-03-29 09:08

MOT test number 476951565747

Result X Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2017-03-08 13:08

MOT test number 867863496854

Result
✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

\sim	MID.	~ r	hi	cti	- m
יטי	wn	er.	ш	SU	ע וכ

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
HARMAN CONTRACTOR CONT	
THE STREET STREE	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	ZIN ZIN
Plate since	
Current registration	UK NIV.
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13




report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-03-28
Last registration	2024-02-13
Complete history	See info



Registration #1	2014-03-28	8 mi
Registration #2	2017-03-08	31.420 mi
Registration #3	2018-03-29	40.867 mi
Registration #4	2018-04-04	40.984 mi
Registration #5	2019-03-29	50.261 mi
Registration #6	2019-04-05	50.517 mi
Registration #7	2020-06-11	62.983 mi
Registration #8	2020-06-11	62.984 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		
Registration #15		

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Adult	75%
Children	80%
Pedestrian	60%
Safety systems	38%
Overall rating	65%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Wheel base	2725 mm
Kerb weight	1261 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	2 page 13	3/13

Number of axles 2

Engine number D397398