






report date: 2024-03-28

General information

Make	RENAULT
Model	MASTER LM35 BUSINESS ENERGY DCI
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	2.298 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	39.2 mpg
CO2 emission	186 g/km
CO2 label	J



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2022-05-10

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2022-01-07
Pictures	12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-07-04
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	6
Total items failed	6

MOT #6	2023-07-05 14:28
MOT test number	216319391708
Result	✓ Passed
Next expiry date	2024-07-04

MOT #5	2022-05-18 16:39
MOT test number	569471838261
Result	✓ Passed
Advice Park brake effort - just met requirements	

MOT #4	2022-05-18 16:00
MOT test number	154541224002
Result	X Failed
Advice Park brake effort - just met requirements	
Fail Nearside Rear Tyre has ply or cords exposed cut in tread (5.2.3 (d) (ii))	
Advice Offside Rear tyre - low tread depth	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2021-12-16 12:52

MOT test number 647317078225

Result X Failed

Advice Offside Rear low tread depth - 2mm

Fail Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

Fail Nearside Outline marker lamp not working x 1 (4.2.1 (a) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Outline marker lamp not working x 2 (4.2.1 (a) (ii))

Fail Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

MOT #2 2020-12-11 09:44

MOT test number 705167143125

Result ✓ Passed

Minor Nearside Front Outline marker lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #1 2019-12-04 09:44

MOT test number 594576471727

Result ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check

Tax expired: 1 March 2024





Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim		ner	L	: -+		
	W/I	1er	-101	ısı	\mathbf{a}	IΛ

,		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-12-13
Last registration	2023-07-05
Complete history	See info



Registration #1	2016-12-13	23 mi
Registration #2	2019-12-04	105.358 mi
Registration #3	2020-12-11	127.574 mi
Registration #4	2021-12-16	144.333 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11,117 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2470 mm
Height	2496 mm
Length	6198 mm
Kerb weight	2029 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	3
Engine number	C010998

CarCheck.co.uk page 11/11