



report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 30 L1H1 100 SWB PV
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-26
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	47
Total items failed	18

MOT #19	2023-10-05 08:58
MOT test number	884625790780
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2023-09-29 14:47

MOT test number

278936272989

Result**✗ Failed****Fail** Offside Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**Fail** Offside Rear Outer Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting x2 (6.2.2 (d) (ii))**Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**Fail** Offside Front Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Outer Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**Fail** Offside Rear Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #17**

2022-09-29 14:59

MOT test number

687344905756

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16

2022-09-29 13:52

MOT test number

787227279500

Result

✗ Failed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15

2021-09-27 15:43

MOT test number

454207390330

Result

✓ Passed

**MOT #14**

2020-08-12 17:59

MOT test number

716892235649

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Exhaust has a minor leak of exhaust gases rear box (6.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge all tyres on 2mm (5.2.3 (e))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #13**

2019-09-02 14:58

MOT test number

616151143071

Result

✓ Passed

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12**

2019-08-12 15:35

MOT test number

927026716495

Result

✗ Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #11** 2018-05-01 14:01**MOT test number** 569704589201**Result** ✓ Passed**Advice** Offside rear tyre perished**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Centre exhaust outer skin deteriorated**MOT #10** 2018-05-01 09:02**MOT test number** 252312973286**Result** ✗ Failed**Advice** Offside rear tyre perished**Fail** Registration plate lamp not working Both (1.1.C.1d)**Advice** Centre exhaust outer skin deteriorated**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2017-04-24 08:04**MOT test number** 457719191437**Result** ✓ Passed**Advice** Rear tyres perishing**Advice** Offside front tyre has wear at inner edge

**MOT #8** 2017-04-24 08:04**MOT test number** 938311990685**Result** ✗ Failed**Advice** Offside front tyre has wear at inner edge**Pass with rectification** Registration plate lamp not working Both (1.1.C.1d)**Advice** Rear tyres perishing**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #7** 2016-03-22 14:06**MOT test number** 946097468058**Result** ✓ Passed**Advice** Rear tyres slightly perished**MOT #6** 2016-03-22 09:06**MOT test number** 762147278756**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear tyres slightly perished**MOT #5** 2015-02-19 15:42**MOT test number** 648610955013**Result** ✓ Passed**MOT #4** 2014-01-14 12:21**MOT test number** 148994214497**Result** ✓ Passed



MOT #3	2014-01-14 12:21
MOT test number	329174114028
Result	✗ Failed
Pass with rectification	Offside Body has a sharp edge caused by damage (6.1.C.1)

MOT #2	2012-10-02 09:26
MOT test number	155746472283
Result	✓ Passed
Advice	Offside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
Notice	Spare wheel loose in its carrier
Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #1	2011-06-08 12:20
MOT test number	928839151114
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 October 2024

Tax status		Valid until 1 January
Days left		246
MOT expiry date		4 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	WR08NCO
Plate since	2019-03-29
Current registration	WR08NCO
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-27
Last registration	2023-10-05
Complete history	See info



Registration #1	2008-05-27	16 mi
Registration #2	2011-06-08	30.592 mi
Registration #3	2012-10-02	46.338 mi
Registration #4	2014-01-14	57.347 mi
Registration #5	2015-02-19	64.630 mi
Registration #6	2016-03-22	69.565 mi
Registration #7	2016-03-22	69.565 mi
Registration #8	2017-04-24	77.550 mi
Registration #9	2017-04-24	77.550 mi
Registration #10	2018-05-01	84.533 mi
Registration #11	2019-05-20	91.517 mi
Registration #12	2019-05-20	91.517 mi
Registration #13	2019-05-20	91.517 mi
Registration #14	2019-05-20	91.517 mi
Registration #15	2019-05-20	91.517 mi
Registration #16	2019-05-20	91.517 mi
Registration #17	2019-05-20	91.517 mi
Registration #18	2019-05-20	91.517 mi
Registration #19	2019-05-20	91.517 mi
Registration #20	2019-05-20	91.517 mi

More info >



Dimensions & weight

Width	2508 mm
Height	2254 mm
Length	4963 mm
Kerb weight	1845 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ10242931