





report date: 2024-03-28

General information

Make	MAZDA
Model	3 SE-L NAV
Colour	Silver
Year of manufacture	2016
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP	
Max. torque	210 Nm at 4.000 rpm	
Engine capacity	1.998 сс	
Cylinders	4	
Fuel type	Petrol	
Consumption city	39.8 mpg	
Consumption extra urban	61.4 mpg	
Consumption combined	51.4 mpg	
CO2 emission	129 g/km	
CO2 label	D	



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-06-03
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-06
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	16
Total items failed	2

MOT #9		2023-06-07 15:42
MOT test	number	498672143253
Result		✓ Passed
Next expi	ry date	2024-06-06
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (a) (ii))	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d slightly pitted (1.1.14
Advice (a) (ii))	Nearside Rear Brake disc worn, pitted or scored, but not seriously weaken	ed slightly pitted (1.1.14

MOT #8		2023-06-07 09:06
MOT test number	er	404018470404
Result		X Failed
Advice Offsic	de Front Tyre slightly damaged/cracking or perishing (5.2.3 (d)	(ii))
Advice Nears (a) (ii))	side Rear Brake disc worn, pitted or scored, but not seriously w	reakened slightly pitted (1.1.14
DANGEROUS	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a)	(ii))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mr	m (5.2.3 (e))
Advice Offsion (a) (ii))	de Rear Brake disc worn, pitted or scored, but not seriously wea	akened slightly pitted (1.1.14

CarCheck.co.uk page 3/12



Result

GF66HJK report date: 2024-03-28

× Failed

MOT #7 2022-05-31 15:23 MOT test number 980951638601

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2022-05-31 14:08

MOT test number 125507003560

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2021-06-07 08:23

MOT test number 297018643068

Result \(\sqrt{Passed} \)

MOT #4 2021-06-07 08:23

MOT test number 813724003066

Result X Failed

Pass with rectification Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))

MOT #3 2020-09-25 12:46

MOT test number 692328660796

Advice Under trays and covers fitted

CarCheck.co.uk page 4/12



MOT #2

MOT test number

401332782518

Result

Advice Rear brake disc faces in poor condition

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))

Advice

Rear brake disc faces in poor condition

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK NK
	UK
Plate since	
Current registration	AIS OK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-10-19
Last registration	2023-06-07
Complete history	See info



Registration #1	2016-10-19	23 mi
Registration #2	2019-10-15	8.225 mi
Registration #3	2019-10-15	8.225 mi
Registration #4	2020-09-25	13.990 mi
Registration #5		11.777 es
Registration #6	2021-06-07	17.635 mi
Registration #7		9.777 es
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		0.00 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2830 mm
Kerb weight	1300 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	PE 20801763

CarCheck.co.uk page 12/12