



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER HDI SE
Colour	Grey
Year of manufacture	2007
Top speed	119 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	46
Total items failed	11

MOT #19	2024-03-19 13:38
MOT test number	712823425141
Result	✓ Passed
Next expiry date	2025-04-04
Advice	Fuel filler pipe perished recommend replacement
Advice	Nearside Play in steering rack inner joint(s)
Advice	Engine cover & undertray fitted obscuring view

MOT #18	2023-04-05 09:40
MOT test number	542537253967
Result	✓ Passed
Advice	Underside corroding
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Play in steering rack inner joint(s)

**MOT #17** 2023-04-04 08:47**MOT test number** 409648143746**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Play in steering rack inner joint(s)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Underside corroding**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #16** 2022-04-05 10:50**MOT test number** 586993301648**Result** ✓ Passed**MOT #15** 2021-09-21 10:35**MOT test number** 525241930436**Result** ✓ Passed**MOT #14** 2020-10-20 13:06**MOT test number** 541688219549**Result** ✓ Passed**MOT #13** 2019-09-26 16:00**MOT test number** 108617453379**Result** ✓ Passed**Advice** Tailgate slightly loose catch and cross member loose (6.2.1 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing tyre wall (5.2.3 (d) (ii))**Advice** Nearside Play in steering rack inner joint(s)

**MOT #12**

2019-09-26 10:41

**MOT test number**

600885027910

**Result****✗ Failed**

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Tailgate slightly loose catch and cross member loose (6.2.1 (a) (i))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing tyre wall (5.2.3 (d) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #11**

2018-09-29 09:29

**MOT test number**

387182784378

**Result****✓ Passed**

- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #10**

2018-09-28 10:27

**MOT test number**

317602263444

**Result****✗ Failed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #9** 2017-10-11 09:23**MOT test number** 577845852456**Result** ✓ Passed**MOT #8** 2015-12-02 15:33**MOT test number** 954108021480**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-12-02 10:32**MOT test number** 101340231096**Result** ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm inner edge delaminating (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-12-09 09:50**MOT test number** 249563644339**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #5** 2013-12-10 11:28**MOT test number** 649604343348**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #4** 2012-09-04 13:57**MOT test number** 195198442281**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Airbag light on
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front tyre wearing on outer edge



MOT #3	2011-10-26 13:32
MOT test number	426059691211
Result	✓ Passed

MOT #2	2011-10-26 12:16
MOT test number	159909691265
Result	✗ Failed
<div><div>Fail</div>Nearside Stop lamp not working (1.2.1b)</div>	

MOT #1	2010-11-12 15:12
MOT test number	273766610381
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
4 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	4 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-11-08
Last registration	2024-03-19
Complete history	<a href="#">See info</a>



Registration #1	2007-11-08	18 mi
Registration #2	2010-11-12	18.891 mi
Registration #3	2011-10-26	26.788 mi
Registration #4	2011-10-26	26.788 mi
Registration #5	2012-09-04	33.286 mi
Registration #6	2013-12-10	42.302 mi
Registration #7	2014-12-09	47.293 mi
Registration #8	2015-12-02	52.858 mi
Registration #9	2015-12-02	52.858 mi
Registration #10	2017-10-11	56.219 mi
Registration #11	2018-09-28	59.307 mi
Registration #12	2019-09-28	62.395 mi
Registration #13	2019-09-28	62.395 mi
Registration #14	2019-09-28	62.395 mi
Registration #15	2019-09-28	62.395 mi
Registration #16	2019-09-28	62.395 mi
Registration #17	2019-09-28	62.395 mi
Registration #18	2019-09-28	62.395 mi
Registration #19	2019-09-28	62.395 mi
Registration #20	2019-09-28	62.395 mi
Registration #21	2019-09-28	62.395 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4676 mm
Wheel base	2725 mm
Kerb weight	1512 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	JB603121909