



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Grey
Year of manufacture	2008
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





MOT history

MOT expiry date	2021-02-05
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	10

MOT #142020-02-06 16:06

MOT test number895275542535

Result✓ Passed

Next expiry date2021-02-05

- Advice

Offside Vehicle structure is corroded but structural rigidity is not significantly reduced outer sill going soft (6.1.1 (c) (i))
- Advice

Child Seat fitted not allowing full inspection of adult belt
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Play in steering rack inner joint(s)

**MOT #13**

2020-01-30 12:29

**MOT test number**

850016148195

**Result****✗ Failed**

**Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced outer sil going soft (6.1.1 (c) (i))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Play in steering rack inner joint(s)

**Fail** Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced outer sil corroded holed and rest of sil going soft (6.1.1 (c) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2019-01-23 16:35

**MOT test number**

522882670264

**Result****✓ Passed**

**Advice** Play in steering rack inner joint(s)

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced lower outer sil (6.1.1 (c) (i))

**MOT #11**

2019-01-23 10:47

**MOT test number**

283043204231

**Result**

✗ Failed

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced lower outer sill (6.1.1 (c) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Play in steering rack inner joint(s)**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #10**

2018-01-09 10:45

**MOT test number**

367501250267

**Result**

✓ Passed

**MOT #9**

2017-02-15 10:54

**MOT test number**

340592156478

**Result**

✓ Passed

**Advice** Both rear tyres out of shape on inner edges**Advice** Heat shield under bonnet loose**MOT #8**

2016-03-02 15:47

**MOT test number**

104308343916

**Result**

✓ Passed

**MOT #7** 2016-03-02 12:23**MOT test number** 681834542067**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2015-02-23 16:58**MOT test number** 186324555456**Result** ✓ Passed**Notice** Mount on rear silencer is excessively corroded but exhaust is secure at time of test**MOT #5** 2015-02-19 09:47**MOT test number** 109580755499**Result** ✗ Failed**Notice** Mount on rear silencer is excessively corroded but exhaust is secure at time of test**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #4** 2014-03-04 10:40**MOT test number** 169003264427**Result** ✓ Passed**MOT #3** 2013-01-21 11:51**MOT test number** 218331823098**Result** ✓ Passed**MOT #2** 2012-01-17 10:18**MOT test number** 588297612044**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2011-01-17 11:22
MOT test number	815437711056
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
23 December 2020

✕  
MOT

Expired:  
5 February 2021

Tax status	Expired at 23 December 2020
Days left	1223 days too late
MOT expiry date	5 February 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-02-27
Last registration	2020-02-06
Complete history	<a href="#">See info</a>



Registration #1	2008-02-27	7 mi
Registration #2	2011-01-17	19.598 mi
Registration #3	2012-01-17	33.159 mi
Registration #4	2013-01-21	47.010 mi
Registration #5	2014-03-04	60.822 mi
Registration #6	2015-02-19	72.124 mi
Registration #7	2015-02-23	72.127 mi
Registration #8	2016-03-02	90.264 mi
Registration #9	2016-03-02	90.264 mi
Registration #10	2016-03-02	90.264 mi
Registration #11	2016-03-02	90.264 mi
Registration #12	2016-03-02	90.264 mi
Registration #13	2016-03-02	90.264 mi
Registration #14	2016-03-02	90.264 mi
Registration #15	2016-03-02	90.264 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBAW0023020