





General information

Make	MERCEDES
Model	E E240 AVANTGARDE
Colour	Silver
Year of manufacture	2000
Top speed	139 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	240 Nm at 4.500 rpm
Engine capacity	2.597 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.6 mpg
Consumption extra urban	38.2 mpg
Consumption combined	27.4 mpg





Internet history

Entry 3

Date Pictures 2021-10-19

8

Listing price

~

View report



source: autotrader.co.uk

Entry 2	
Date	2021-10-19
Pictures	8
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-09-07
Pictures	8
Listing price	View report









source: autotrader.co.uk





MOT history

MOT expiry date	2024-04-07
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	21
Total items failed	11

MOT #21	2023-03-31 08:53
MOT test number	560447376442
Result	✓ Passed
Next expiry date 2024-04-0	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #20	2022-03-30 10:03
MOT test number	928336364880
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resultin (5.3.4 (a) (i))	ng in excessive movement

MOT #19	2022-03-28 11:11
MOT test number	661712382983
Result	🗙 Failed
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting i (5.3.4 (a) (i))	n excessive movement
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough (5.2.3 (d) (i))	to reach the ply or cords
Fail Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e	e))





MOT #18	2021-04-08 08:50
MOT test number	287873429934
Result	✓ Passed
MOT #17	2021-04-08 08:50
MOT test number	366564435493
Result	× Failed
Pass with rectification	Nearside Front Headlamp aim projected beam image is obviously incorrect

(4.1.2 (c))

MOT #16		2019-06-10 13:44
MOT test	number	870659134625
Result		✓ Passed
Advice	Offside mirror glass slightly derteriorated	
Advice	Brake pipe corroded, covered in grease or other material both 'front to rears'	'(1.1.11(c))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front fog light in-operative	
Advice	Rear Brake pipe corroded, covered in grease or other material Both sides (1.	1.11 (c))

MOT #15	2018-05-26 10:48
MOT test number	670404014145
Result	✓ Passed
MOT #14	2017-05-23 13:31
	70511700000

MOT test number	735117332006
Result	✓ Passed

MOT #13	2016-06-13 05:14
MOT test number	345172182908
Result	✓ Passed





MOT #12		2014-12-01 18:22
MOT test	number	595625534312
Result		✓ Passed
Notice	Offside front and rear tyres and nearside rear tyre has cracks	
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	

MOT #11	2014-11-27 13:05
MOT test number	148231734346
Result	🗙 Failed
Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Notice Offside front and rear tyres and nearside rear tyre has cracks	
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	

MOT #10		2013-11-27 16:00
MOT test	number	519261033361
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Notice	Oil leak	
Notice	Items removed from driver's view prior to test	

МОТ #9	2012-11-26 13:26
MOT test number	756271832375
Result	✓ Passed





MOT #8	3	2012-11-26 10:55
MOT te	st number	506791432353
Result		🗙 Failed
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail	Rear registration plate character(s) incorrectly spaced (6.3.4a)	
Fail	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail	Front registration plate character(s) incorrectly spaced (6.3.4a)	

MOT #7	2011-11-26 13:09
MOT test number	636060631337
Result	✓ Passed
Advice Rear Direction indicators slightly discoloured (1.4.A.2f)	

МОТ #6	2010-11-29 10:33
MOT test number	733213030343
Result	✓ Passed
Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)	

MOT #5	2010-11-29 10:33	
MOT test number	171303330304	
Result	× Failed	
Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)		

MOT #4	2009-11-07 14:28
MOT test number	601901419337
Result	✓ Passed






MOT #3	2008-11-28 15:36
MOT test number	190143138301
Result	✓ Passed
MOT #2	2007-11-23 14:02
MOT test number	423417927454
Result	✓ Passed
Notice Engine management on	
MOT #1	2006-11-11 12:04
MOT test number	474495816493
Result	✓ Passed





Tax & MOT check







Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	A A A A A A A A A A A A A A A A A A A
Category	AMPL
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ACCOUNTS AND A DESCRIPTION OF A DESCRIPR	
And a second sec	

NUMBER OF TAXABLE PARTY	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2000-09-01
Last registration	2023-03-31
Complete history	See info



Registration #1	2000-09-01	13 mi
Registration #2	2006-11-11	5.319 mi
Registration #3	2007-11-23	5.650 mi
Registration #4	2008-11-28	6.833 mi
Registration #5	2009-11-07	10.392 mi
Registration #6	2010-11-29	14.001 mi
Registration #7	2011-11-26	14.825 mi
Registration #8	2012-11-26	18.368 mi
Registration #9	2012-11-26	18.368 mi
Registration #10	2013-11-27	21.307 mi
Registration #11	2014-11-27	23.785 mi
Registration #12	2014-12-01	23.792 mi
Registration #13		11.117 esi
Registration #13 Registration #14		11.227 est
		01,000 est 01,000 est 01,000 est
Registration #14		01,000 est 01,000 est 01,000 est 01,000 est
Registration #14 Registration #15		01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6
Registration #14 Registration #15 Registration #16		00.000 e60 01.000 e60 01.000 e60 01.000 e60 01.000 e60 01.000 e60 01.000 e60
Registration #14 Registration #15 Registration #16 Registration #17		01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6 01,000 e6
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		00,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		00,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		00.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		00.000 440 00.000 440







Dimensions & weight

Width	1980 mm
Height	1440 mm
Length	4818 mm
Wheel base	2833 mm

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	11291430863580