



SG58GSU

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 SPORT LR P/V
Colour	Blue
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	350 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT expiry date	2021-02-25
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	11
Total items failed	19

MOT #16	2020-02-14 10:18
MOT test number	774979373886
Result	✓ Passed
Next expiry date	2021-02-25
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #15	2019-02-26 17:04
MOT test number	285500792136
Result	✓ Passed

MOT #14	2019-02-26 17:04
MOT test number	327707514417
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #13** 2018-02-05 14:25**MOT test number** 794938466983**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #12** 2017-02-18 10:25**MOT test number** 735939063960**Result** ✓ Passed**MOT #11** 2017-02-18 10:25**MOT test number** 206157259593**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**MOT #10** 2016-02-20 12:11**MOT test number** 510654362512**Result** ✓ Passed**MOT #9** 2016-02-20 12:11**MOT test number** 599960112697**Result** ✗ Failed**Pass with rectification** Offside Front Front wheel bearing rough when rotated (2.5.A.2)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)

**MOT #8** 2015-05-29 16:51**MOT test number** 727739345120**Result** ✓ Passed**MOT #7** 2014-07-11 11:08**MOT test number** 535732894129**Result** ✓ Passed**Notice** Gear box mounts worn**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-07-04 14:46**MOT test number** 876235184158**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Notice** Gear box mounts worn**Fail** Brake pipe excessively corroded (3.6.B.2c)

**MOT #5** 2013-06-12 14:58**MOT test number** 895703563129**Result** ✓ Passed**MOT #4** 2012-07-19 12:43**MOT test number** 146481902278**Result** ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2012-07-19 03:36**MOT test number** 387061902268**Result** ✗ Failed

Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside front brake binding (3.7.B.1)

MOT #2 2011-09-01 14:46**MOT test number** 146074641209**Result** ✓ Passed**MOT #1** 2011-08-22 15:17**MOT test number** 715054731267**Result** ✗ Failed

Fail Centre Stop lamp not working (1.2.1b)

Fail Offside Rear rear parking brake recording little or no effort (3.7.B.6a)

Fail Nearside Rear Leaf spring cracked (2.4.B.1a)



Tax & MOT check

✕
Untaxed

Tax expired:
1 September 2021

✕
MOT

Expired:
25 February 2021

Tax status	Expired at 1 September
Days left	971 days too late
MOT expiry date	25 February 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SG58GSU
Plate since	2019-03-28
Current registration	SG58GSU
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-10-21
Last registration	2020-02-14
Complete history	See info



Registration #1	2008-10-21	14 mi
Registration #2	2011-08-22	27.420 mi
Registration #3	2011-09-01	27.455 mi
Registration #4	2012-07-19	31.566 mi
Registration #5	2012-07-19	31.567 mi
Registration #6	2013-06-12	33.962 mi
Registration #7	2014-07-04	53.786 mi
Registration #8	2014-07-11	53.786 mi
Registration #9	2015-05-29	68.490 mi
Registration #10	2015-05-29	68.490 mi
Registration #11	2015-05-29	68.490 mi
Registration #12	2015-05-29	68.490 mi
Registration #13	2015-05-29	68.490 mi
Registration #14	2015-05-29	68.490 mi
Registration #15	2015-05-29	68.490 mi
Registration #16	2015-05-29	68.490 mi
Registration #17	2015-05-29	68.490 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1974 mm
Height	2067 mm
Length	4863 mm
Wheel base	2933 mm
Kerb weight	1710 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	8Y32525