



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	White
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-04
Pictures	3
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #11	2022-07-12 11:27
MOT test number	813620901341
Result	✓ Passed
Next expiry date	2023-07-14
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Subframe mounting repair covered in underseal (5.3.6 (a) (i))

MOT #10	2021-06-18 09:48
MOT test number	729060977803
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #9	2020-07-15 16:08
MOT test number	412605641999
Result	✓ Passed
Advice	N/s/f tyre is wearing on the inner edge
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Corrosion to exhaust
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Engine cover fitted
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	O/s/f tyre is wearing on the inner edge
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8**

2020-07-15 11:15

MOT test number

986504737344

Result

✗ Failed

Advice

Engine cover fitted

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice

O/s/f tyre is wearing on the inner edge

Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail

Nearside Position lamp not working (4.2.1 (a) (ii))

Advice

N/s/f tyre is wearing on the inner edge

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Corrosion to exhaust

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7

2019-08-24 10:33

MOT test number

337175524669

Result

✓ Passed

Advice

Undertray fitted

Advice

Engine cover fitted

Advice

N/s/f lower suspension arm bush is deteriorating slightly

Advice

O/s/r shock absorber appears to have been leaking

Advice

N/s/f lower suspension arm bush is deteriorating slightly

MOT #6

2018-08-25 10:21

MOT test number

847251638257

Result

✓ Passed

**MOT #5** 2018-07-03 08:29**MOT test number** 449565187847**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge wear (5.2.3 (e))**MOT #4** 2017-08-11 13:56**MOT test number** 768036205391**Result** ✓ Passed**MOT #3** 2016-08-12 14:55**MOT test number** 818405050012**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Advise small cuts on nearside front tyre**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2015-03-19 09:52**MOT test number** 909588675094**Result** ✓ Passed**MOT #1** 2014-02-24 08:59**MOT test number** 858245954002**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY60CCX
Plate since	2019-09-29
Current registration	YY60CCX
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-10-12
Last registration	2022-07-12
Complete history	See info



Registration #1	2010-10-12	23 mi
Registration #2	2014-02-24	53.536 mi
Registration #3	2015-03-19	58.456 mi
Registration #4	2016-08-12	74.827 mi
Registration #5	2017-08-11	90.746 mi
Registration #6	2018-07-03	107.422 mi
Registration #7	2018-08-25	110.701 mi
Registration #8	2019-05-20	121.277 mi
Registration #9	2019-05-20	121.277 mi
Registration #10	2019-05-20	121.277 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1361361