



SC66SGU

report date: 2024-03-28

General information

Make	NISSAN
Model	LEAF ACENTA
Colour	White
Year of manufacture	2017
Top speed	87 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity




LABEL UNKNOWN



Internet history

Entry 2


Date	2021-07-28
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-18
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-05
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #6 2023-08-05 10:49

MOT test number 727689841288

Result ✓ Passed

Next expiry date 2024-08-05

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm (5.3.4 (a) (i))

Advice Offside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair hand brake/foot brake (1.2.1 (c))

MOT #5 2022-07-30 09:33

MOT test number 628183054948

Result ✓ Passed

MOT #4 2021-08-06 13:43

MOT test number 705903437008

Result ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement starting to perish and split (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement starting to perish and split (5.3.4 (a) (i))

**MOT #3** 2020-12-11 13:18**MOT test number** 127443800281**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2020-01-24 11:28**MOT test number** 689524643849**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #1** 2020-01-24 11:28**MOT test number** 193158734919**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
5 August 2024

Tax status	Valid until 1 December
-------------------	------------------------

Days left	216
------------------	-----

MOT expiry date	5 August 2024
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-01-25
Last registration	2023-08-05
Complete history	See info



Registration #1	2017-01-25	23 mi
Registration #2	2020-01-24	29.825 mi
Registration #3	2020-01-24	29.825 mi
Registration #4	2020-12-11	35.033 mi
Registration #5	2023-08-05	35.033 mi
Registration #6	2023-08-05	35.033 mi
Registration #7	2023-08-05	35.033 mi
Registration #8	2023-08-05	35.033 mi
Registration #9	2023-08-05	35.033 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1538 kg
Max. allowed weight	1945 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	082481Z
---------------	---------