





report date: 2024-03-28

### General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Silver
Year of manufacture	2008
Top speed	72 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	196 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-10-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

MOT expiry date	2024-10-06
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #17		2023-09-28 09:17
MOT test	number	287911909927
Result		✓ Passed
Next expi	ry date	2024-10-06
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #16	2022-10-03 16:1	9
MOT test	<b>number</b> 91315503507	5
Result	✓ Passe	d
Advice	Passenger seat(s) missing at time of test 3rd row	
Advice (e))	Nearside Rear Tyre worn close to legal limit/worn on edge wearing slightly on inside edge (5.2.3	

MOT #15		2022-10-03 16:19
MOT test number		889663464857
Result		<b>×</b> Failed
Advice Nearside Rear Ty	yre worn close to legal limit/worn on edge	wearing slightly on inside edge (5.2.3
Pass with rectification	Offside Front Position lamp not working	(4.2.1 (a) (ii))
Advice Passenger seat(s	s) missing at time of test 3rd row	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice Coil spring corroded rear both (5.3.1 (b) (i))

Advice Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn slightly (5.1.2 (b) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2020-12-22 16:30 **MOT** test number 233221247936 Result × Failed Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11	2019-05-02 09:36
MOT test number	861304033941
Result	<b>✓</b> Passed
MOT #10	2018-10-15 09:20
MOT test number	770127599652
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9	2017-10-30 10:51
MOT test number	525312075073
Result	<b>✓</b> Passed
MOT #8	2016-10-25 09:37
MOT test number	819336148827
Result	✓ Passed
MOT #7	2015-11-02 13:14
MOT test number	930545096849
Result	✓ Passed
MOT #6	2014-10-13 11:48
MOT test number	179836584218
Result	✓ Passed
MOT #5	2013-10-21 11:43
MOT test number	508184893253
Result	<b>✓</b> Passed
MOT #4	2012-10-22 10:35
MOT test number	415876792256
Result	✓ Passed
MOT #3	2011-10-25 11:21
MOT test number	367298091469
Result	✓ Passed
	v i usseu
MOT #2	2010-11-03 10:49
MOT test number	584337700326
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2010-11-03 10:10

**MOT test number** 222807300336

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/13





report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	6 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



OV57WTF
report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners d Check it in the premium report and see all owner registrations. Download the full report h		ave?
*******		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	NK NY	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



OV57WTF report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-03
Last registration	2023-09-28
Complete history	See info



Registration #1	2008-01-03	13 mi
Registration #2	2010-11-03	41.461 mi
Registration #3	2010-11-03	41.462 mi
Registration #4	2011-10-25	48.397 mi
Registration #5	2012-10-22	56.042 mi
Registration #6	2013-10-21	64.247 mi
Registration #7	2014-10-13	72.524 mi
Registration #8	2015-11-02	81.239 mi
Registration #9	2016-10-25	88.280 mi
Registration #10	2017-10-30	95.507 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		D.777 es
Registration #19		10.707 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 13/13