





## General information

| Make                | AUDI                   |
|---------------------|------------------------|
| Model               | A4 TDI QUATTRO S LINE  |
| Colour              | White                  |
| Year of manufacture | 2017                   |
| Top speed           | 146 mph                |
| Gearbox             | 7 speed Semi-Automatic |

# Engine & fuel consumption

| Power                   | 188 BHP             |
|-------------------------|---------------------|
| Max. torque             | 400 Nm at 1.750 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 54.3 mpg            |
| Consumption extra urban | 68.9 mpg            |
| Consumption combined    | 62.8 mpg            |
| CO2 emission            | 121 g/km            |
| CO2 label               | D                   |





## Internet history

| Entry 1       |             |
|---------------|-------------|
| Date          | 2021-05-21  |
| Pictures      | 29          |
| Listing price | View report |









source: autotrader.co.uk



## MOT history

| MOT expiry date    | 2024-06-06 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 2          |
| Total advice items | 15         |
| Total items failed | 5          |

| МОТ #6   | 2023-06-07 17:14 |
|--|------------------|
| MOT test number  | 606663834677     |
| Result   | Passed           |
| Next expiry date   | 2024-06-06       |
| <ul> <li>Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Both track control arm bushes slightly worn-perished (5.3.4 (a) (i))</li> <li>Advice Offside Front Shock absorbers has a slightly worn bush bottom bush (5.3.2 (c))</li> <li>Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Both track control arm bushes slightly worn-perished (5.3.4 (a) (i))</li> </ul> |                  |
| Advice Nearside Front Shock absorbers has a slightly worn bush bottom bush   | n (5.3.2 (c))    |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |                  |

| MOT #5  |  | 2022-05-06 14:54 |
|---|--|------------------|
| MOT test  | number   | 320934457324     |
| Result  |  | ✓ Passed         |
| Advice Nearside Front Shock absorbers has a slightly worn bush bottom bush in arm (5.3.2 (c)) |  |                  |
| Advice  | Front Brake disc worn, but not excessively x2 (1.1.14 (a) (i))                   |                  |
| Advice  | Offside Front Shock absorbers has a slightly worn bush bottom bush in arm (5.3.2 | 2 (c))           |





| MOT #4   | 2022-05-05 15:07 |  |
|--|------------------|--|
| MOT test number  | 550289853034     |  |
| Result   | 🗙 Failed         |  |
| <b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))                    |                  |  |
| Advice Front Brake disc worn, but not excessively x2 (1.1.14 (a) (i))                          |                  |  |
| Advice Offside Front Shock absorbers has a slightly worn bush bottom bush in arm (5.3.2 (c))   |                  |  |
| FailRear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))                           |                  |  |
| <b>Fail</b> Front Windscreen wiper does not clear the windscreen effectively x2 (3.4 (b) (ii)) |                  |  |
| Advice Nearside Front Shock absorbers has a slightly worn bush bottom bush in arm (5           | 5.3.2 (c))       |  |
| Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))                               |                  |  |

| MOT #3  | 2021-04-29 21:31 |
|---|------------------|
| MOT test number   | 159858066503     |
| Result  | 🗙 Failed         |
| Advice Front tyres treads low os vns                                      |                  |
| Fail Nearside Front Windscreen in an unacceptable condition (3.2 (c) (i)) |                  |

| MOT #2          | 2021-04-29 21:00 |
|-----------------|------------------|
| MOT test number | 406222089171     |
| Result          | ✓ Passed         |

| MOT #1   |   | 2020-09-29 09:37 |
|----------|---|------------------|
| MOT test | number  | 579333151759     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear Nail in tyre   |                  |
| Advice   | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |



Tax & MOT check

| √<br>Taxed                         | ✓<br>MOT                |
|------------------------------------|-------------------------|
| <b>Tax due:</b><br>1 February 2025 | Expires:<br>6 June 2024 |
| Tax status                         | Valid until 1 February  |
| Days left                          | 277                     |
| MOT expiry date                    | 6 June 2024             |
| Full MOT history                   | See MOT history         |

## Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | G          |
| First licence fee (12 months)                        | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |





### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |      |
|----------|------|
| Date     |      |
| Category | Lamp |
| Туре     |      |
| Damage 2 | AMPL |
| Date     |      |
| Date     | OLE  |
| Category | E.S. |
| Туре     |      |

#### Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 =      |





## Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx  |             |
|---|-------------|
| ************  |             |
| ********  |             |
| *******   |             |
| ***********   |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this AUDI had different number plates. |             |
| Number of plates  | 7           |
| Carrent registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   |             |





#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 8          |
| First mileage registration | 2017-10-20 |
| Last registration          | 2023-06-07 |
| Complete history           | See info   |



| Registration #1 | 2017-10-20 | 17 mi      |
|-----------------|------------|------------|
| Registration #2 | 2020-09-29 | 59.879 mi  |
| Registration #3 | 2021-04-29 | 72.567 mi  |
| Registration #4 | 2021-04-29 | 72.567 mi  |
| Registration #5 |            | 11.777 mi  |
| Registration #6 |            | 11.777 esi |
| Registration #7 |            | 11.777 mi  |
| Registration #8 |            | 11.777 esi |





## Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| S0482  |                  |
| S0501  |                  |
| S0566  |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 93%             |
| Children       | 84%             |
| Pedestrian     | 39%             |
| Safety systems | 71%             |
| Overall rating | 78%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1842 mm          |
| Height                            | 1427 mm          |
| Length                            | 4726 mm          |
| Wheel base                        | 2820 mm          |
| Kerb weight                       | 1575 kg          |
| Max. allowed weight               | 2160 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 58 I             |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 4                |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11     |

| Number of axles | 2          |
|-----------------|------------|
| Engine number   | DETA168743 |