





report date: 2024-03-29

General information

Make	RENAULT	
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S	
Colour	Red	
Year of manufacture	2014	
Top speed	113 mph	
0 - 60 mph	12.2 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-23

Pictures 8

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



SK14FOH report date: 2024-03-29

MOT history

MOT expiry date	2025-01-18
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	16
Total items failed	0

MOT #11	2024-01-19 15:18
MOT test number	491266123800
Result	✓ Passed
Next expiry date	2025-01-18

MOT #10		2024-01-17 13:49
MOT test	number	990018396685
Result		🗙 Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	Offside Front Upper Coil spring mounting damaged but not seriously weakened ((5.3.1 (b) (i))

MOT #9	20	022-12-15 10:00
MOT test	number	431045867262
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Advice Brake pipe corroded, covered in grease or other material brake pipe across rear axle (1.1.11 (c))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.	14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2022-01-07 11:05

MOT test number 183863604111

Result \rightarrow Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #7 2020-12-10 16:44

MOT test number 832492399665

Result \(\sqrt{Passed} \)

MOT #6 2020-12-10 11:55

MOT test number 906470562269

Result X Failed

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot insecure (6.1.7 (g) (ii))

MOT #5 2020-01-04 10:28

MOT test number 743642469339

Result
✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4 2019-04-02 14:40

MOT test number 449163874442

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2019-04-02 10:13

MOT test number 720792197778

Result X Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #2 2018-04-05 12:45

MOT test number 870190744851

Result ✓ Passed

Advice

Child Seat fitted not allowing full inspection of adult belt

MOT #1 2017-03-29 13:49

MOT test number 155771666325

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Pinance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-31
Last registration	2024-01-19
Complete history	See info



Registration #1	2014-03-31	18 mi
Registration #2	2017-03-29	34.621 mi
Registration #3	2018-04-05	43.948 mi
Registration #4	2019-04-02	51.010 mi
Registration #5	2019-04-02	51.010 mi
Registration #6	2020-01-04	55.560 mi
Registration #7	2020-12-10	67.656 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2
Engine number U165424