




report date: 2024-03-28

General information

Make	MINI
Model	COOPER AUTO COOPER
Colour	Black
Year of manufacture	2013
Top speed	122 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2022-02-23
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-15
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	13
Total items failed	5

MOT #11	2023-05-16 15:31
MOT test number	953750353011
Result	✓ Passed
Next expiry date	2024-05-15
Advice	Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2022-04-19 15:44
MOT test number	957928731555
Result	✓ Passed

MOT #9	2021-09-14 09:35
MOT test number	782375507817
Result	✓ Passed

MOT #8	2020-08-07 12:14
MOT test number	881183630246
Result	✓ Passed



MOT #7 2019-06-12 09:15

MOT test number 384715367802

Result ✓ Passed

MOT #6 2018-06-29 09:07

MOT test number 345124762244

Result ✓ Passed

MOT #5 2018-06-26 07:56

MOT test number 971397681807

Result ✗ Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing and has a nail (5.2.3 (d) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing and has 2 nails (5.2.3 (d) (i))

MOT #4 2017-06-28 08:06

MOT test number 678634993414

Result ✓ Passed

Advice Both rear tyres starting to crack

MOT #3 2017-06-27 16:01

MOT test number 637375121126

Result ✗ Failed

Fail Rear fog lamp not working (1.3.2b)

Advice Both rear tyres starting to crack



MOT #2	2016-03-29 12:04
MOT test number	824811979809
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit on legal limit (4.1.E.1)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2016-03-29 12:04
MOT test number	987610301869
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too far to the right (1.8)
Advice	Offside Front Tyre worn close to the legal limit on legal limit (4.1.E.1)
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
15 May 2024

Tax status Valid until 1 October

Days left 155

MOT expiry date 15 May 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check

 If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	LK13UJA
Plate since	2019-09-29
Current registration	LK13UJA
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-01
Last registration	2023-05-16
Complete history	See info



Registration #1	2013-03-01	17 mi
Registration #2	2016-03-29	19.133 mi
Registration #3	2016-03-29	19.133 mi
Registration #4	2017-06-27	24.213 mi
Registration #5	2017-06-28	24.215 mi
Registration #6	2018-06-26	26.543 mi
Registration #7	2018-06-29	26.548 mi
Registration #8	2019-06-29	26.557 mi
Registration #9	2019-06-29	26.557 mi
Registration #10	2019-06-29	26.557 mi
Registration #11	2019-06-29	26.557 mi
Registration #12	2019-06-29	26.557 mi
Registration #13	2019-06-29	26.557 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1105 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles

2

Engine number

A459J424