



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO MULTIAIR GP
Colour	White
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2




Date	2023-04-30
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-02
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-05
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	33
Total items failed	11

MOT #18	2023-05-06 16:07
MOT test number	557464954485
Result	✓ Passed
Next expiry date	2024-05-05
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #17	2023-05-04 11:10
MOT test number	433233572891
Result	✗ Failed
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16	2022-09-12 12:20
MOT test number	581447188783
Result	✓ Passed

**MOT #15**

2021-08-16 10:23

**MOT test number**

560055607381

**Result**

✓ Passed

**Advice** Nearside Rear Shock absorber piston cover missing**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14**

2021-08-16 10:05

**MOT test number**

210831089026

**Result**

✗ Failed

**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Shock absorber piston cover missing**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #13**

2020-08-24 10:07

**MOT test number**

994538717876

**Result**

✓ Passed

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2020-08-24 10:07

**MOT test number**

938043977217

**Result****✗ Failed****Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #11**

2019-08-29 08:01

**MOT test number**

522325898262

**Result****✓ Passed****Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10**

2019-08-29 08:01

**MOT test number**

677296990085

**Result****✗ Failed****Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #9**

2018-08-28 10:14

**MOT test number**

331906269160

**Result****✓ Passed****Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2018-08-28 10:14**MOT test number** 491952869498**Result** ✗ Failed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Nearside Position lamp not working (4.2.1 (a))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #7** 2017-08-21 13:05**MOT test number** 213278405424**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play inner arm (2.2.B.1f)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #6** 2017-08-21 10:55**MOT test number** 329045028577**Result** ✗ Failed**Advice** Offside Front Track rod end ball joint has slight play inner arm (2.2.B.1f)**Advice** Engine light on at time of test**Fail** Offside Headlamp aim too low (1.8)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Fail** Nearside Headlamp aim too low (1.8)**MOT #5** 2016-09-14 11:27**MOT test number** 978433401212**Result** ✓ Passed**Advice** Nearside front anti roll bar link has slight play.

**MOT #4** 2016-03-19 16:42**MOT test number** 313868104978**Result** ✓ Passed**MOT #3** 2015-03-21 09:46**MOT test number** 307810985041**Result** ✓ Passed**MOT #2** 2014-03-15 12:14**MOT test number** 466224674061**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-03-15 07:24**MOT test number** 117034574013**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
5 May 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	5 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-03-21
Last registration	2023-05-06
Complete history	<a href="#">See info</a>



Registration #1	2011-03-21	27 mi
Registration #2	2014-03-15	33.651 mi
Registration #3	2014-03-15	33.657 mi
Registration #4	2015-03-21	41.854 mi
Registration #5	2016-03-19	47.869 mi
Registration #6	2016-09-14	50.735 mi
Registration #7	2017-08-21	56.659 mi
Registration #8	2017-08-21	56.659 mi
Registration #9	2018-08-28	62.757 mi
Registration #10	2018-08-28	62.757 mi
Registration #11	2019-08-29	77.069 mi
Registration #12	2019-08-29	77.069 mi
Registration #13	2019-08-29	77.069 mi
Registration #14	2019-08-29	77.069 mi
Registration #15	2019-08-29	77.069 mi
Registration #16	2019-08-29	77.069 mi
Registration #17	2019-08-29	77.069 mi
Registration #18	2019-08-29	77.069 mi
Registration #19	2019-08-29	77.069 mi
Registration #20	2019-08-29	77.069 mi
Registration #21	2019-08-29	77.069 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1075 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1610550