





report date: 2024-03-28

General information

Make	CITROEN
Model	C2 VT
Colour	Red
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history


Entry 1

Date 2022-01-23


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-18
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	13
Total items failed	5

MOT #15		2024-01-15 10:34
MOT test	number	920039826083
Result		✓ Passed
Next expi	y date	2025-01-18
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriou	sly weakened (1.1.14 (a) (ii))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously	y weakened (1.1.14 (a) (ii))

MOT #14	2023-01-12 08:59
MOT test number	757858119401
Result	✓ Passed
MOT #13	2022-01-19 08:44
MOT test number	148193725558
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2022-01-12 11:49

MOT test number 431500777884

Result X Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #11 2020-12-29 16:16

MOT test number 657563380180

Result ✓ Passed

Advice Items removed from driver's view prior to test

MOT #10 2020-12-29 12:58

MOT test number 305152983237

Result X Failed

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Items removed from driver's view prior to test

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9 2019-09-19 13:54

MOT test number 329914045984

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.6mm. (5.2.3 (e))

CarCheck.co.uk page 4/13



YC59HGN report date: 2024-03-28

MOT #8 2019-09-19 10:50

MOT test number 776174625539

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.6mm. (5.2.3 (e))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #7 2018-10-01 10:41

MOT test number 447123272350

Result \rightarrow Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

(a) (i))

MOT #6 2017-10-02 09:40

MOT test number 376417471848

Result J Passed

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #5 2016-10-11 09:46

MOT test number 544453021794

MOT #4 2015-10-15 09:43

MOT test number 530915743016

MOT #3 2014-10-20 10:11

MOT test number 309203094273

Notice Front brake discs poor

CarCheck.co.uk page 5/13



report date: 2024-03-28

 MOT #2
 2013-10-24 10:50

 MOT test number
 227257093281

 Result
 ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

 MOT #1
 2012-11-01 10:08

 MOT test number
 709636802320

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

_	
Owner	history
OWILL	1113601

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		EN
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-11-03
Last registration	2024-01-15
Complete history	See info



Registration #1	2009-11-03	20 mi
Registration #2	2012-11-01	11.210 mi
Registration #3	2013-10-24	18.583 mi
Registration #4	2014-10-20	22.822 mi
Registration #5	2015-10-15	28.499 mi
Registration #6	2016-10-11	32.467 mi
Registration #7	2017-10-02	34.416 mi
Registration #8	2018-10-01	35.300 mi
Devietueties #0	2010 00 10	38.526 mi
Registration #9	2019-09-19	30.320 1111
Registration #9	2019-09-19	36.320 1111
	2019-09-19	38.320 1111
Registration #10	2019-09-19	38.320 1111
Registration #10 Registration #11	2019-09-19	38.320 1111
Registration #10 Registration #11 Registration #12	2019-09-19	38.320 IIII
Registration #10 Registration #11 Registration #12 Registration #13	2019-09-19	38.320 IIII
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14	2019-09-19	38.320 IIII

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	956 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W5123324

CarCheck.co.uk page 13/13