



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Blue
Year of manufacture	-
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-05
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history****MOT #17** 2020-12-15 13:28**MOT test number** 833830343883**Result** ✓ Passed**Next expiry date** 2021-12-14**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Play in steering rack inner joint(s) both**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #16** 2020-12-09 12:19**MOT test number** 807012938125**Result** ✗ Failed**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Fuel pipe leaking (6.1.3 (b) (i))**Advice** Play in steering rack inner joint(s) both**MOT #15** 2019-06-17 14:15**MOT test number** 444204061869**Result** ✓ Passed**MOT #14** 2018-06-13 11:14**MOT test number** 976280613411**Result** ✓ Passed

**MOT #13**

2018-06-12 12:06

MOT test number

454264781603

Result**✗ Failed**

- Fail** Front Brake disc in such a condition that it is seriously weakened both ns & os (1.1.14 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Rear Brake disc in such a condition that it is seriously weakened both ns & os (1.1.14 (a) (ii))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

MOT #12

2017-06-15 07:51

MOT test number

279679393852

Result**✓ Passed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened all discs (3.5.1i)
- Advice** Rear Tyre worn close to the legal limit both wearing slightly on inner edges (4.1.E.1)

MOT #11

2017-06-15 07:51

MOT test number

129069920646

Result**✗ Failed**

- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all discs (3.5.1i)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Rear Tyre worn close to the legal limit both wearing slightly on inner edges (4.1.E.1)

**MOT #10**

2016-06-13 15:38

MOT test number

315474870799

Result

✓ Passed

- Advice** Both front tyres wearing inside edge
- Advice** Under body covers & under bonnet covers fitted
- Advice** Front and rear brake discs appear corroded

MOT #9

2016-06-13 11:56

MOT test number

391103813212

Result

✗ Failed

- Advice** Front and rear brake discs appear corroded
- Advice** Both front tyres wearing inside edge
- Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Advice** Under body covers & under bonnet covers fitted
- Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

MOT #8

2015-06-09 08:56

MOT test number

145610265132

Result

✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Rear brake discs corroded
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Front brake discs corroded inner edges

**MOT #7**

2014-05-29 09:02

MOT test number

179599244118

Result

✓ Passed

Advice Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Front and rear brake discs corroded**MOT #6**

2013-05-14 09:05

MOT test number

139664533103

Result

✓ Passed

Notice Both front and rear brake discs corroded**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Under-trays fitted obscuring some underside components**Notice** Some distortion both rear wheels**MOT #5**

2012-05-02 12:49

MOT test number

217493222460

Result

✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Rear brake discs corroded**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Front brake discs inner surfaces corroded

**MOT #4** 2012-05-02 12:49**MOT test number** 975933322113**Result** ✗ Failed**Notice** Rear brake discs corroded**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Front brake discs inner surfaces corroded**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2011-02-12 12:35**MOT test number** 979973141097**Result** ✓ Passed**MOT #2** 2011-02-11 12:18**MOT test number** 417052641026**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #1** 2010-03-23 12:51**MOT test number** 161532780416**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-16
Last registration	2020-12-15
Complete history	See info



Registration #1	2007-03-16	16 mi
Registration #2	2010-03-23	26.080 mi
Registration #3	2011-02-11	33.048 mi
Registration #4	2011-02-12	33.048 mi
Registration #5	2012-05-02	38.589 mi
Registration #6	2013-05-14	42.357 mi
Registration #7	2014-05-29	46.079 mi
Registration #8	2015-06-09	48.814 mi
Registration #9	2016-06-13	50.969 mi
Registration #10	2016-06-13	50.969 mi
Registration #11	2016-06-13	50.969 mi
Registration #12	2016-06-13	50.969 mi
Registration #13	2016-06-13	50.969 mi
Registration #14	2016-06-13	50.969 mi
Registration #15	2016-06-13	50.969 mi
Registration #16	2016-06-13	50.969 mi
Registration #17	2016-06-13	50.969 mi
Registration #18	2016-06-13	50.969 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm

Additional information

Number of seats	4
Number of axles	2
Engine number	NOT KNOWN