



GDI4RJZ


report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history


Entry 2

Date	2023-12-05
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-07-20
Pictures	10
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-07-25
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	13
Total items failed	9

MOT #11 2023-07-24 10:17

MOT test number 702439519846

Result ✓ Passed

Next expiry date 2024-07-25

Advice Rear Suspension component corroded but not seriously weakened All rear suspension components show general signs of corrosion (5.3.3 (b) (i))

MOT #10 2022-07-18 10:11

MOT test number 370704922877

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Rear discs slightly worn (1.1.14 (a) (ii))

MOT #9 2021-07-26 14:20

MOT test number 237662677336

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2021-01-04 15:15**MOT test number** 565614733769**Result** ✓ Passed**MOT #7** 2021-01-04 11:50**MOT test number** 879347903653**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**MOT #6** 2020-01-06 15:47**MOT test number** 778222443557**Result** ✓ Passed**MOT #5** 2019-01-08 10:26**MOT test number** 793528025579**Result** ✓ Passed**MOT #4** 2019-01-04 09:17**MOT test number** 802376544001**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #3** 2018-07-13 16:30**MOT test number** 844066590293**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Engine cover & under tray fitted obscuring some components**MOT #2** 2017-08-10 10:44**MOT test number** 276449676401**Result** ✓ Passed**MOT #1** 2017-06-20 11:08**MOT test number** 114969144810**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear tyre has cuts in tread patterns**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front headlamp light density lower then off side headlamp**Fail** Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	GD14RJZ
Plate since	2019-03-28
Current registration	GD14RJZ
Plate since	2019-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-06-30
Last registration	2023-07-24
Complete history	See info



Registration #1	2014-06-30	10 mi
Registration #2	2017-06-20	48.687 mi
Registration #3	2017-08-10	49.436 mi
Registration #4	2018-07-13	61.821 mi
Registration #5	2019-01-04	65.591 mi
Registration #6	2019-01-08	65.818 mi
Registration #7	2020-01-06	72.944 mi
Registration #8	2020-01-06	72.944 mi
Registration #9	2020-01-06	72.944 mi
Registration #10	2020-01-06	72.944 mi
Registration #11	2020-01-06	72.944 mi
Registration #12	2020-01-06	72.944 mi
Registration #13	2020-01-06	72.944 mi
Registration #14	2020-01-06	72.944 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT