




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI SE SPORT
Colour	Black
Year of manufacture	2005
Top speed	114 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	36.2 mpg
Consumption combined	28.8 mpg
CO2 emission	265 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-07-30
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-15
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	35
Total items failed	7

MOT #18 2023-07-11 15:16**MOT test number** 582486408931**Result** ✓ Passed**Next expiry date** 2024-07-15

- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Seat belt flexible stalk damaged (7.1.2 (b) (i))
- Advice** Nearside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Offside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17 2022-07-16 09:29**MOT test number** 109377959527**Result** ✓ Passed

- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Exhaust emits black smoke during acceleration (8.2.1.2 (g))

MOT #16 2021-01-22 16:03**MOT test number** 887227999353**Result** ✓ Passed

**MOT #15**

2021-01-13 10:50

MOT test number

124014949374

Result

✗ Failed

Fail Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Brake performance not tested (1.2.1 (g))**MOT #14**

2019-07-08 09:59

MOT test number

386986489164

Result

✓ Passed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13**

2018-07-05 13:53

MOT test number

458150118898

Result

✓ Passed

Advice Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #12**

2018-07-03 15:58

MOT test number

129554043704

Result

✗ Failed

Fail Offside Front Power steering pipe/hose leaking metal pipe from steering rack (2.1.5 (a))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11** 2017-07-12 15:24**MOT test number** 268554370369**Result** ✓ Passed**Advice** Under trays fitted**MOT #10** 2016-08-16 09:38**MOT test number** 536897725680**Result** ✓ Passed**MOT #9** 2015-07-24 10:13**MOT test number** 526445805207**Result** ✓ Passed**Notice** Damage to offside rear seat belt stork cover**MOT #8** 2014-08-14 17:23**MOT test number** 589686024246**Result** ✓ Passed**Notice** Under trays fitted**MOT #7** 2013-08-01 12:48**MOT test number** 825433813274**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2013-07-30 10:54**MOT test number** 197181313220**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2012-08-17 10:39**MOT test number** 316190932228**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Inner Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear brake disc outer surfaces corroding**Advice** Nearside Inner Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2011-07-19 13:06**MOT test number** 529410401246**Result** ✓ Passed**Notice** Nearside rear tyre worn on outer edge**Notice** Nearside rear brake disc pitted**Notice** Offside front tyre worn on inner edge**Notice** Offside rear brake disc pitted



MOT #3 2010-07-19 15:08

MOT test number 923630700235

Result ✓ Passed

Notice Very serious coolant leak from heater pipes under nearside front wing

Notice Both rear disc's corroding

Notice Under trays fitted (unable to fully inspect underside for corrosion to fuel pipes-brake lines and chassis)

MOT #2 2009-07-29 16:12

MOT test number 412370119211

Result ✓ Passed

Notice All brake discs poor surface condition and rusty.

MOT #1 2008-07-15 11:53

MOT test number 291567998136

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
15 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	15 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-07-19
Last registration	2023-07-11
Complete history	See info



Registration #1	2005-07-19	29 mi
Registration #2	2008-07-15	19.555 mi
Registration #3	2009-07-29	24.353 mi
Registration #4	2010-07-19	29.256 mi
Registration #5	2011-07-19	34.648 mi
Registration #6	2012-08-17	39.728 mi
Registration #7	2013-07-30	44.981 mi
Registration #8	2013-08-01	44.981 mi
Registration #9	2014-08-14	50.424 mi
Registration #10	2015-07-24	55.935 mi
Registration #11	2016-07-24	61.446 mi
Registration #12	2017-07-24	66.957 mi
Registration #13	2018-07-24	72.468 mi
Registration #14	2019-07-24	77.979 mi
Registration #15	2020-07-24	83.490 mi
Registration #16	2021-07-24	89.001 mi
Registration #17	2022-07-24	94.512 mi
Registration #18	2023-07-11	100.023 mi
Registration #19	2024-03-29	105.534 mi
Registration #20	2024-03-29	111.045 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1723 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2510 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BAC 067042