





report date: 2024-03-28

### General information

| Make                | TOYOTA                       |
|---------------------|------------------------------|
| Model               | HIACE 280 GS SWB P/V (88BHP) |
| Colour              | Blue                         |
| Year of manufacture | 2004                         |
| Gearbox             | 5 speed Manual               |

# Engine & fuel consumption

| Power                  | 88 BHP              |
|------------------------|---------------------|
| Max. torque            | 192 Nm at 1.200 rpm |
| <b>Engine capacity</b> | 2.494 сс            |
| Cylinders              | 4                   |
| Fuel type              | Diesel              |



CarCheck.co.uk page 1/12



report date: 2024-03-28


# Internet history

### Entry 1

Date 2021-09-21

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date    | 2022-08-15 |
|--------------------|------------|
| no rexpiry date    | 2022 00 13 |
| MOT pass rate      | 88 %       |
| MOT passed         | 15         |
| Failed MOT tests   | 2          |
| Total advice items | 16         |
| Total items failed | 3          |

| MOT #17   | 2021-08-16 13:36 |
|---|------------------|
| MOT test number   | 411919333800     |
| Result  | ✓ Passed         |
| Next expiry date  | 2022-08-15       |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |                  |

| MOT #16    |   | 2020-07-28 07:53 |
|------------|---|------------------|
| MOT test i | number  | 155194561582     |
| Result     |   | ✓ Passed         |
| Advice     | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c) | )                |

| MOT #15  |   | 2019-07-31 08:20 |
|----------|---|------------------|
| MOT test | number  | 264643219375     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c) | )                |
| Advice   | Rear axle ( differential ) support mount deteriorated but not excessively         |                  |

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

194623096080

Result

Pass with rectification (b) (ii))

Advice Rear axle ( differential ) support mount deteriorated but not excessively

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

 MOT #13
 2018-07-25 11:52

 MOT test number
 411791734636

 Result
 ✓ Passed

 MOT #12
 2017-07-27 10:17

MOT test number 642518902658

Result 
✓ Passed

**MOT #11** 2016-08-03 09:02

MOT test number 774826178015

Result 

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #10 2015-09-05 08:52

MOT test number 636385690987

Result / Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #9 2014-08-22 06:58

**MOT test number** 325814334287

**Result** ✓ Passed

Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #8 2013-08-24 12:23

**MOT test number** 979706433231

**Result** ✓ Passed

MOT #7 2012-08-16 11:32

**MOT test number** 898139022224

Result \rightarrow Passed

MOT #6 2011-08-19 15:00

MOT test number 347881431203

Result 

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #5 2011-08-18 10:42

MOT test number 796790631217

**Result** ★ Failed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

MOT #4 2010-08-09 16:26

**MOT test number** 232241220235

Result 

Passed

CarCheck.co.uk page 5/12



| MOT #3   |   | 2009-08-19 11:29 |
|----------|---|------------------|
| MOT test | number  | 874111439231     |
| Result   |   | <b>✓</b> Passed  |
| Notice   | Chip in windscreen in zone "b" not yet large enough to fail |                  |
| Notice   | N/s/f lock stop cover has worn down to metal                |                  |
| Notice   | All wipers not clearing screen very well                    |                  |
| Notice   | Handbrake has play in cable                                 |                  |

| MOT #2          | 2008-08-20 10:58 |
|-----------------|------------------|
| MOT test number | 451203738214     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2007-08-13 14:50 |
| MOT test number | 554565127293     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 6/12



### Tax & MOT check





| 25 September 2021 | 15 August 2022          |
|-------------------|-------------------------|
| Tax status        | Expired at 25 September |
| Days left         | 946 days too late       |
| MOT expiry date   | 15 August 2022          |
| Full MOT history  | See MOT history         |

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



More info >

| Owner history   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this TOYOTA? How many owners have? Check it in the premium report and see all owner registrations. Download the full re |             |
| *********   |             |
|   |             |
| ************  |             |
| HARMAN AND AND AND AND AND AND AND AND AND A  |             |
|   |             |
| ************  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this TOYOTA had different number plates.   |             |
| Number of plates  |             |
| Current registration  | NE NE       |
| Plate since   |             |
| Current registration  | UK AIS      |
| Plate since   |             |

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 10/12



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 19         |
| First mileage registration | 2004-08-26 |
| Last registration          | 2021-08-16 |
| Complete history           | See info   |



| Registration #1  | 2004-08-26 | 23 mi      |
|------------------|------------|------------|
| Registration #2  | 2007-08-13 | 60.606 mi  |
| Registration #3  | 2008-08-20 | 79.176 mi  |
| Registration #4  | 2009-08-19 | 97.823 mi  |
| Registration #5  | 2010-08-09 | 112.943 mi |
| Registration #6  | 2011-08-18 | 126.963 mi |
| Registration #7  | 2011-08-19 | 126.963 mi |
| Registration #8  | 2012-08-16 | 140.511 mi |
| Registration #9  | 2013-08-24 | 152.076 mi |
| Registration #10 | 2014-08-22 | 164.032 mi |
| Registration #11 |            | 11.777 es  |
| Registration #12 |            | 11.777 es  |
| Registration #13 |            | 11.777 es  |
| Registration #14 |            | 11.777 es  |
| Registration #15 |            | 9.70 es    |
| Registration #16 |            | 11.777 es  |
| Registration #17 |            | 11.777 es  |
| Registration #18 |            | 11.777 es  |
| Registration #19 |            |            |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Additional information

| Fuel tank capacity | 75 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of seats    | 3                |
| Engine number      | 2KD1159402       |

CarCheck.co.uk page 12/12