





report date: 2024-03-28

General information

Make	BMW
Model	218 218I LUXURY GRAN TOURER
Colour	White
Year of manufacture	2018
Top speed	126 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-07-29

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-28

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-25
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	3
Total items failed	5

MOT #6	2024-01-25 10:36
MOT test number	308590401185
Result	✓ Passed
Next expiry date	2025-01-25
Advice Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #5	2023-01-25 13:26
MOT test number	661945113503
Result	✓ Passed

MOT #4	1	2023-01-25 11:23
MOT te	st number	378164812185
Result		🗙 Failed
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its st	ructure (5.2.3 (d) (ii))
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))		
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Advic	e Offside Front Tyre slightly damaged (5.2.3 (d) (ii))	

MOT #3	2022-01-25 12:44
MOT test number	281832975465
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #2 2022-01-25 10:05

MOT test number 536291882134

Result

X Failed

Fail Nearside Front Road wheel fixing missing wheel bolt missing (5.2.1 (a) (i))

Fail Nearside Front Body panel damaged and likely to cause injury headlamp lens broken causing a sharp edge (6.2.1 (a) (i))

MOT #1 2021-01-08 12:24

MOT test number 195682983687

Result ✓ Passed

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NIX.
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-01-26
Last registration	2024-01-25
Complete history	See info



Registration #1	2018-01-26	22 mi
Registration #2	2021-01-08	14.640 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5	2022-01-25	24.651 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1612 mm
Length	4556 mm
Wheel base	2780 mm
Kerb weight	1475 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	51
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles2Engine number30235214