



RA53TZR

report date: 2024-03-28

General information

Make	HONDA
Model	STREAM SE SPORT
Colour	Grey
Year of manufacture	-
Top speed	127 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.8 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-01-17
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-09
Pictures	29
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #21	2022-05-30 12:21
MOT test number	647497393244
Result	✓ Passed
Next expiry date	2023-05-29

MOT #20	2022-05-27 15:07
MOT test number	630573393241
Result	✗ Failed

- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #19	2021-07-08 11:51
MOT test number	773943234442
Result	✓ Passed

MOT #18	2020-09-12 14:25
MOT test number	142544058931
Result	✓ Passed

MOT #17	2019-04-27 13:14
MOT test number	787529821502
Result	✓ Passed

**MOT #16** 2018-05-07 13:10**MOT test number** 412181128000**Result** ✓ Passed**MOT #15** 2017-05-06 12:30**MOT test number** 953479370607**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #14** 2016-06-18 08:36**MOT test number** 818474645935**Result** ✓ Passed**MOT #13** 2015-07-25 09:37**MOT test number** 667746005216**Result** ✓ Passed**MOT #12** 2014-05-24 12:00**MOT test number** 279344844430**Result** ✓ Passed**MOT #11** 2014-05-24 09:37**MOT test number** 325024944153**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage severely distorted (2.4.G.1)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #10	2013-05-04 10:03
----------------	------------------

MOT test number	537174723137
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2012-05-19 14:38
---------------	------------------

MOT test number	627650542111
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2011-05-07 13:29
---------------	------------------

MOT test number	158757721188
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2010-05-20 14:24
---------------	------------------

MOT test number	690020240195
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2010-05-20 13:27
---------------	------------------

MOT test number	752340340183
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5	2009-04-02 10:52
---------------	------------------

MOT test number	363502699007
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2008-03-12 11:07
---------------	------------------

MOT test number	852452478021
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #3	2007-04-12 15:01
MOT test number	383972107105
Result	✓ Passed
MOT #2	2006-10-31 13:18
MOT test number	603114906383
Result	✓ Passed
MOT #1	2006-10-31 13:18
MOT test number	874654506375
Result	✗ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	RA53TZR
Plate since	2019-09-29
Current registration	RA53TZR
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-10-29
Last registration	2022-05-30
Complete history	See info



Registration #1	2003-10-29	23 mi
Registration #2	2006-10-31	30.737 mi
Registration #3	2007-04-12	35.263 mi
Registration #4	2008-03-12	37.458 mi
Registration #5	2009-04-02	41.651 mi
Registration #6	2010-05-20	45.191 mi
Registration #7	2010-05-20	45.191 mi
Registration #8	2011-05-07	47.849 mi
Registration #9	2012-05-19	50.727 mi
Registration #10	2013-05-04	56.760 mi
Registration #11	2014-05-24	64.082 mi
Registration #12	2014-05-24	64.084 mi
Registration #13	2015-05-20	65.277 mi
Registration #14	2016-05-20	65.277 mi
Registration #15	2017-05-20	65.277 mi
Registration #16	2018-05-20	65.277 mi
Registration #17	2019-05-20	65.277 mi
Registration #18	2020-05-20	65.277 mi
Registration #19	2021-05-20	65.277 mi
Registration #20	2022-05-20	65.277 mi
Registration #21	2023-05-20	65.277 mi
Registration #22	2024-05-20	65.277 mi
Registration #23	2025-05-20	65.277 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1924 mm
Height	1590 mm
Length	4570 mm
Wheel base	2720 mm
Kerb weight	1425 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	K20A13001181