





report date: 2024-03-28

### General information

Make	MAZDA
Model	6 SE-L NAV
Colour	Blue
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	118 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

### Entry 2

Date 2021-09-09

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

Entry 1

Date	2021-09-09
Pictures	21

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

MOT expiry date	2024-09-22
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #6		2023-09-08 12:11
MOT test	number	384747836976
Result		<b>✓</b> Passed
Next expi	ry date	2024-09-22
Advice	Offside Rear Nail in tyre	
Advice	Both rear tyres cracking/perishing	
Advice	Brake pad(s) wearing thin front brake pads getting low (1.1.13 (a) (ii))	

MOT #5	2023-09-08 10:27	
MOT test number	857644021023	
Result	<b>×</b> Failed	
Fail Offside Front Anti-roll bar ball joint excessively worn drop link play in ball joint (5.3.4 (a) (i))		
Advice Brake pad(s) wearing thin front brake pads getting low (1.1.13 (a) (ii))		
Advice Offside Rear Nail in tyre		
Advice Both rear tyres cracking/perishing		

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT #4** 2022-09-22 10:18 561762952162 **MOT** test number Result ✓ Passed **Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT** #3 2021-09-23 13:32 **MOT** test number 222929192864 Result ✓ Passed **MOT #2** 2021-03-18 11:44 **MOT test number** 636954341476 ✓ Passed Result **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1		2020-03-26 10:39
MOT test	number	231870180404
Result		<b>✓</b> Passed
Advice	Plastic Covers Fitted	
Advice	Tyre slightly damaged/cracking or perishing OSF/NSF (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	22 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners of have? Check it in the premium report and see all owner registrations. Download the full re		A
THE REAL PROPERTY AND ADDRESS OF THE PERTY		
***************************************		
***************************************		
THE PROPERTY OF THE PROPERTY O		
	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	NK SIZ	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-29
Last registration	2023-09-08
Complete history	See info



Registration #1	2017-03-29	16 mi
Registration #2	2020-03-26	20.788 mi
Registration #3	2021-03-18	24.981 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		0.00 44
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



# Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1795 mm
Height	1465 mm
Length	4465 mm
Wheel base	2700 mm
Kerb weight	1386 kg
Max. allowed weight	1835 kg

# Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 20953354

CarCheck.co.uk page 11/11