





General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 207 ACTIVE |
| Colour | Red |
| Year of manufacture | 2011 |
| Top speed | 104 mph |
| 0 - 60 mph | 15.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 73 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 3.300 rpm |
| Engine capacity | 1.360 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 145 g/km |
| CO2 label | F |





SAGI PK

Internet history

Entry 1

Date Pictures 2021-08-06

17

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-05-16 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 10 |
| Failed MOT tests | 5 |
| Total advice items | 16 |
| Total items failed | 12 |

| MOT #15 | 2023-05-17 15:45 |
|------------------|------------------|
| MOT test number | 216006084548 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-16 |

| MOT #14 | 2023-05-16 15:36 |
|--|------------------|
| MOT test number | 957079493104 |
| Result | 🗙 Failed |
| Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |

| MOT #13 | 2022-08-11 11:02 |
|--|------------------|
| MOT test number | 500078638162 |
| Result | ✓ Passed |
| AdviceRear axle slightly corrodedAdviceFront Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Auvice Front On leak, but not excessive (6.4.1 (a) (i)) | |
| MOT #12 | 2021-08-14 08.54 |

| | 2021-00-14 00.34 |
|-----------------|------------------|
| MOT test number | 359675706125 |
| Result | ✓ Passed |





| MOT #11 | 2021-08-09 12:28 |
|---|------------------|
| MOT test number | 631045715466 |
| Result | 🗙 Failed |
| Fail Power steering malfunctioning (2.1.5 (a)) | |
| MOT #10 | 2021-04-23 10:35 |
| MOT test number | 411361023568 |
| Result | 🗙 Failed |
| Fail Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i)) | |
| Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt cv boot insecure (6.1.7 (g) (ii)) | |
| Fail Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i)) | |
| Fail Power steering inoperative and steering adversely affected (2.1.5 (c) (ii)) | |

| MOT #9 | 2020 | -03-11 10:25 |
|----------|---|--------------|
| MOT test | number 20 | 4221230284 |
| Result | | 🗸 Passed |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a | a) (ii)) |



SA61PKC report date: 2024-03-28

| MOT #8 | 2020-03-10 16:13 |
|---|-------------------|
| MOT test number | 616917197355 |
| Result | 🗙 Failed |
| Fail Brake lever has insufficient reserve travel (1.1.2 (a)) | |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1 | .1.14 (a) (ii)) |
| FailOffside Rear Direction indicator incorrect colour (4.4.3 (a)) | |
| Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no lo ingress of dirt outer clip broken (6.1.7 (g) (ii)) | nger prevents the |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1 | .14 (a) (ii)) |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a)) | |

| MOT #7 | 2019-03-06 08:49 |
|-----------------|------------------|
| MOT test number | 176167555160 |
| Result | ✓ Passed |
| | |

| MOT #6 | 2019-03-05 09:29 | |
|---|------------------|--|
| MOT test number | 707864182700 | |
| Result | 🗙 Failed | |
| Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) | | |
| Advice Oil leak, but not excessive Sump corroded & porous (8.4.1 (a) (i)) | | |





| MOT #5 | | 2018-07-25 14:41 |
|------------------------|--|----------------------------------|
| MOT test | number | 352727403225 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in ex | cessive movement (5.3.4 (a) |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in e | excessive movement (5.3.4 |
| MOT #4 | | 2017 07 17 12.20 |
| MOT #4 MOT test | aumhor | 2017-07-17 13:36 927216747234 |

Result

| MOT #3 | 2016-07-06 13:26 |
|--|------------------|
| MOT test number | 913563037403 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #2 | 2015-07-28 14:08 |
|-----------------|------------------|
| MOT test number | 336089305490 |
| Result | ✓ Passed |
| | |

| MOT #1 | 2014-09-27 11:24 |
|-------------------------------|------------------|
| MOT test number | 347880474278 |
| Result | ✓ Passed |
| Notice Exhaust bracket broken | |

🗸 Passed



Tax & MOT check

| ✓ Taxed Tax due: 1 November 2024 | MOT Expires: 16 May 2024 |
|---|--------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 16 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plata since | |
| | |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2011-09-26 |
| Last registration | 2023-05-17 |
| Complete history | See info |



| Registration #1 | 2011-09-26 | 20 mi |
|------------------|------------|------------|
| Registration #2 | 2014-09-27 | 20.911 mi |
| Registration #3 | 2015-07-28 | 25.362 mi |
| Registration #4 | 2016-07-06 | 29.845 mi |
| Registration #5 | 2017-07-17 | 35.611 mi |
| Registration #6 | 2018-07-25 | 38.478 mi |
| Registration #7 | 2019-03-05 | 39.659 mi |
| Registration #8 | 2019-03-06 | 39.659 mi |
| Registration #9 | 2020-03-10 | 44.173 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 mi |
| | | |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| 50566 | |
| 50567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1920 mm |
| Height | 1502 mm |
| Length | 4030 mm |
| Wheel base | 2540 mm |
| Kerb weight | 1229 kg |
| Max. allowed weight | 1601 kg |
| Additional information | |
| Fuel tank capacity | 50 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 5 page 13/13 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | FSX46458693 |