





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI SE NAV BLUE DRIVE
Colour	Black
Year of manufacture	2015
Top speed	119 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	280 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



EY65HKC

report date: 2024-03-29


Internet history

Entry 1

Date 2021-08-01

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



EY65HKC

report date: 2024-03-29

MOT history

MOT expiry date	2023-10-19
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	7
Total items failed	3

MOT #8		2022-10-20 15:28
MOT test	number	263860160613
Result		✓ Passed
Next expi	ry date	2023-10-19
Advice	Under body slightly corroded	
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduce	ed (6.1.1 (c) (i))

MOT #7	2022-10-20 15:18
MOT test number	198725360898
Result	🗙 Failed
Advice Under body slightly corroded	
Fail Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))	
Advice Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6	6.1.1 (c) (i))

MOT #6	2021-08-25 15:25
MOT test number	378689891867
Result	✓ Passed

CarCheck.co.uk page 3/11



EY65HKC

report date: 2024-03-29

MOT #5 2021-08-12 14:52

MOT test number 743950177632

Result × Failed

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #4 2021-01-08 09:06

MOT test number 553294988557

Result ✓ Passed

MOT #3 2021-01-05 13:17

MOT test number 295472304666

Result X Failed

Fail Offside Rear Suspension arm insecure and impairing directional stability bolt insecure nut missing (5.3.3 (a) (ii))

MOT #2 2019-06-11 10:02

MOT test number 105135102446

Result

Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2018-05-03 15:56

MOT test number 996524280605

Result
✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check

Tax expired: 18 May 2023



X MOT

Expired: 19 October 2023

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 18 May 2023

348 days too late

19 October 2023

See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >
	Piolo inio

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-04
Last registration	2022-10-20
Complete history	See info



Registration #1	2015-09-04	9 mi
Registration #2	2018-05-03	35.194 mi
Registration #3	2019-06-11	51.952 mi
Registration #4	2021-01-05	79.123 mi
Registration #5	2021-01-08	79.135 mi
Registration #6		D.777 es
Registration #7		91.777 es
Dogistration #9		
Registration #8		
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4745 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number D4FDFU545699