





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI STYLE
Colour	Black
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history

Entry 2

Date 2023-11-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

71.	2021 03 21	
Date	2021-05-21	

Pictures 37

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-05
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	18
Total items failed	4

MOT #11	2023-11-06 14:01
MOT test number	987851284141
Result	✓ Passed
Next expiry date	2024-11-05

MOT #	10	2023-11-03 11:22
MOT te	est number	821417698523
Result		X Failed
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #9	2023-03-27 15:07
MOT test number	800151128017
Result	✓ Passed
Advice Power steering noisy	

CarCheck.co.uk page 3/12



MOT #6

EO62VBN

report date: 2024-03-29

2021-04-09 16:23

MOT test number

Fail Nearside Front Service brake excessively binding (1.2.1 (f))

Advice Power steering noisy

Fail Offside Front Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT test number

S84295284746

Result

Advice Slight movement in in steering wheel detected when engine running

Advice Nearside Service brake binding but not excessively (1.2.1 (f))

Minor Offside Front Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT test number	735695119149
Result	✓ Passed
MOT #5	2019-08-30 07:34
MOT test number	572658422142
Result	✓ Passed
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT test number

Result

Advice Nearside Rear Nail in tyre

Advice Play in steering rack inner joint(s)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number
986345641550

Result

Advice Offside Front tyre gauged not showing cords

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Nail in tyre

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2015-08-13 11:22

 MOT test number
 544176246182

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	5 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

EO62VBN

report date: 2024-03-29

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HY have? Check it in the premium report and see all owner registrations. Download the full report here .	'UNDAI

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-06
Last registration	2023-11-06
Complete history	See info



Registration #1	2012-09-06	19 mi
Registration #2	2015-08-13	27.176 mi
Registration #3	2016-09-05	34.977 mi
Registration #4	2017-09-07	43.316 mi
Registration #5	2018-09-04	51.320 mi
Registration #6	2019-08-30	59.124 mi
Registration #7	2021-04-09	65.828 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 p	age 12/12

Number of axles 2

Engine number D4FDBU063639