



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SE V50
Colour	Red
Year of manufacture	2005
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H







Internet history

Entry 3

Date 2021-07-05

Pictures 9

Listing price [View report](#)





source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2021-06-28

Pictures 9

Listing price [View report](#)





source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-06-21

Pictures 9

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-14
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	43
Total items failed	5

MOT #18	2023-11-15 09:09
MOT test number	318838069022
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Slight exhaust blow
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front exhaust mount broken
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Both front suspension lower arm rear mounting bushes worn

MOT #17	2022-10-17 13:16
MOT test number	805757575793
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2019-07-03 11:14

MOT test number

294494329732

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15

2019-07-02 09:30

MOT test number

488837927604

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2018-06-29 13:48

MOT test number

617728993235

Result

✓ Passed

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2018-06-28 11:10**MOT test number** 367344750616**Result** ✗ Failed**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2017-06-27 15:29**MOT test number** 235646744256**Result** ✓ Passed**Advice** Oil leak**MOT #11** 2017-06-22 12:44**MOT test number** 563422560025**Result** ✗ Failed**Advice** Oil leak**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #10** 2016-06-30 07:09**MOT test number** 230640105854**Result** ✓ Passed

**MOT #9** 2015-06-30 10:36**MOT test number** 796431285168**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Oil leak**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8** 2014-07-01 16:31**MOT test number** 197122484170**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-09-11 11:29**MOT test number** 139494953283**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Brake servo hose appears to be slightly deteriorated**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #6** 2012-09-26 09:53**MOT test number** 387390372473**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Front brake application only just passed
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Notice** Tyre size 205/50r17 93w

MOT #5 2011-09-23 15:00**MOT test number** 388676561239**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #4 2010-09-28 14:57**MOT test number** 364471570452**Result** ✓ Passed**MOT #3** 2009-09-30 11:30**MOT test number** 333903079410**Result** ✓ Passed



MOT #2	2009-09-30 11:30
MOT test number	991103479274
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)

MOT #1	2008-09-25 12:00
MOT test number	560009968218
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	OV55CXG
Plate since	2019-03-29
Current registration	OV55CXG
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-30
Last registration	2023-11-15
Complete history	See info



Registration #1	2005-09-30	19 mi
Registration #2	2008-09-25	22.768 mi
Registration #3	2009-09-30	30.617 mi
Registration #4	2010-09-28	37.318 mi
Registration #5	2011-09-23	43.490 mi
Registration #6	2012-09-26	51.179 mi
Registration #7	2013-09-11	57.038 mi
Registration #8	2014-07-01	61.947 mi
Registration #9	2015-06-30	71.645 mi
Registration #10	2016-06-30	85.569 mi
Registration #11	2017-06-22	87.963 mi
Registration #12	2018-06-22	91.377 mi
Registration #13	2019-06-22	95.791 mi
Registration #14	2020-06-22	100.205 mi
Registration #15	2021-06-22	104.619 mi
Registration #16	2022-06-22	109.033 mi
Registration #17	2023-06-22	113.447 mi
Registration #18	2024-06-22	117.861 mi
Registration #19	2025-06-22	122.275 mi
Registration #20	2026-06-22	126.689 mi
Registration #21	2027-06-22	131.103 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1402 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	33276