



Mercedes-Benz




report date: 2024-03-28

General information

| | |
|---------------------|----------------------------------|
| Make | MERCEDES-BENZ |
| Model | A-CLASS A 200 D AMG LINE PREMIUM |
| Colour | Black |
| Year of manufacture | 2019 |
| Top speed | 137 mph |
| 0 - 100 km/h | 8.3 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|----------------------|---------------------------|
| Power | 110 kW / 150 HP / 148 BHP |
| Max. torque | 320 Nm at 3.200 rpm |
| Engine capacity | 1.950 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 56.5 mpg |
| CO2 emission | 110 g/km |
| CO2 label | B |







Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-12-07 |
| Pictures | 18 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-07 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-02-21 |
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 6 |
| Total items failed | 0 |

MOT #3 2024-02-19 11:46**MOT test number** 489467720919**Result** Passed**Next expiry date** 2025-02-21**Advice** Rear Tyre slightly damaged/cracking or perishing both sides inside tread (5.2.3 (d) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner tread 1.6mm and inner tread wearing on edge (5.2.3 (e))**MOT #2** 2023-02-22 11:48**MOT test number** 859636492082**Result** Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))**MOT #1** 2021-12-03 09:53**MOT test number** 249842696745**Result** Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
21 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 December |
| Days left | 217 |
| MOT expiry date | 21 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2020-01-01 |
| Current registration | XXXXXX |
| Plate since | 2020-01-01 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2019-03-27 |
| Last registration | 2024-02-19 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-03-27 | 20 mi |
| Registration #2 | 2021-12-03 | 18.552 mi |
| Registration #3 | 2023-05-20 | 20,000 mi |
| Registration #4 | 2023-05-20 | 20,000 mi |
| Registration #5 | 2023-05-20 | 20,000 mi |
| Registration #6 | 2023-05-20 | 20,000 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 96% |
| Children | 91% |
| Pedestrian | 92% |
| Safety systems | 75% |
| Overall rating | 90% |
| Video | see crash video |



Dimensions & weight

| | |
|-------------|---------|
| Width | 1796 mm |
| Height | 1440 mm |
| Length | 4419 mm |
| Wheel base | 2 mm |
| Kerb weight | 1390 kg |

Additional information

| | |
|-----------------|----------------|
| Number of axles | 2 |
| Engine number | 65492080588736 |