



SD64EYL

report date: 2024-03-28

General information

Make	CITROEN
Model	C3 HDI VTR PLUS PICASSO
Colour	Grey
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	312 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-03
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #9	2024-04-02 08:18
MOT test number	511037546785
Result	✓ Passed
Next expiry date	2025-04-03

MOT #8	2023-04-04 13:05
MOT test number	296432416654
Result	✓ Passed

MOT #7	2022-03-25 15:30
MOT test number	893237090379
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear exhaust hangar broken and front partially broken

**MOT #6** 2022-03-25 15:30**MOT test number** 531752491072**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear exhaust hangar broken and front partially broken**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #5** 2021-03-25 11:43**MOT test number** 727258626450**Result** ✓ Passed**MOT #4** 2021-03-25 08:46**MOT test number** 362024439221**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #3** 2019-09-27 13:51**MOT test number** 974299650465**Result** ✓ Passed**Advice** Rear Exhaust mounting defective (6.1.2 (a))



MOT #2	2018-09-06 10:40
MOT test number	265636209470
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2017-09-18 14:32
MOT test number	372758181895
Result	✓ Passed



Tax & MOT check

✓

Taxed

Tax due:
1 April 2025

✓

MOT

Expires:
3 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	SD64EYL
Plate since	2019-03-28
Current registration	SD64EYL
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-30
Last registration	2024-04-02
Complete history	See info



Registration #1	2014-09-30	25 mi
Registration #2	2017-09-18	29.170 mi
Registration #3	2018-09-06	38.914 mi
Registration #4	2019-09-27	49.472 mi
Registration #5	2020-03-25	56.048 mi
Registration #6	2021-03-25	56.048 mi
Registration #7	2021-03-25	56.048 mi
Registration #8	2021-03-25	56.048 mi
Registration #9	2021-03-25	56.048 mi
Registration #10	2021-03-25	56.048 mi
Registration #11	2021-03-25	56.048 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1404 kg
Max. allowed weight	1779 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFM0120939