



PF590EK

report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER HARD TOP
Colour	Green
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	27.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-11
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	38
Total items failed	3

MOT #17	2023-12-09 08:49
MOT test number	901530278788
Result	✓ Passed
Next expiry date	2024-12-08

MOT #16	2023-01-31 07:39
MOT test number	819833703989
Result	✓ Passed

MOT #15	2022-02-14 17:22
MOT test number	106645835093
Result	✓ Passed

MOT #14	2021-12-09 10:25
MOT test number	589165193546
Result	✓ Passed

MOT #13	2020-12-21 14:54
MOT test number	339555472261
Result	✓ Passed



MOT #12	2020-12-21 10:34
MOT test number	725636437254
Result	✗ Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Minor	Rear Registration plate lamp throwing direct white light to the rear (4.7.1 (a))

MOT #11	2019-11-14 13:23
MOT test number	994460020835
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Brake pipe corroded, covered in grease or other material front to rear pipe(to flexi pipe) (1.1.11 (c))

**MOT #10**

2019-11-12 16:02

MOT test number

660161018548

Result**✗ Failed**

- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Front Windscreen washer not working (3.5 (a))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush upper and lower bushes (5.3.2 (c))
- MAJOR** Nearside Front Seat belt retracting mechanism defective (7.1.2 (e))
- Advice** Long park brake travel
- Advice** Brake pipe corroded, covered in grease or other material front to rear pipe(to flexi pipe) (1.1.11 (c))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- DANGEROUS** Stop lamp(s) all not working (4.3.1 (a) (iii))
- MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Shock absorbers has a slightly worn bush upper and lower (5.3.2 (c))
- MAJOR** Speedometer cannot be illuminated (7.8 (c) (ii))

**MOT #9** 2018-11-14 16:43**MOT test number** 409782042754**Result** ✓ Passed

- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Inner Brake pad(s) wearing thin getting low (1.1.13 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))
- Advice** Clutch pedal rubber missing

MOT #8 2017-11-24 12:12**MOT test number** 818780988106**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Shock absorber has a slightly worn bush top and bottom bushes (2.7.4)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Offside Rear Shock absorber has a slightly worn bush top and bottom bushes (2.7.4)

MOT #7 2016-11-18 15:49**MOT test number** 249446647271**Result** ✓ Passed

- Advice** Rear Tyre worn close to the legal limit Both Sides (4.1.E.1)
- Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)

**MOT #6** 2015-12-22 12:27**MOT test number** 326950624751**Result** ✓ Passed**Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)**MOT #5** 2015-12-22 12:27**MOT test number** 795214104528**Result** ✗ Failed**Pass with rectification** Offside Front Seat belt stitching badly frayed (5.2.2b)**Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)**MOT #4** 2014-12-22 13:14**MOT test number** 519276254315**Result** ✓ Passed**MOT #3** 2014-12-20 10:50**MOT test number** 328534254349**Result** ✗ Failed**Fail** Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-12-19 14:36**MOT test number** 577063253352**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)



MOT #1	2013-01-18 11:49
MOT test number	138928113457
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 December 2024

Tax status		Valid until 1 January
Days left		246
MOT expiry date		8 December 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	PF590EK
Plate since	2024-03-29
Current registration	PF590EK
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-01-27
Last registration	2023-12-09
Complete history	See info



Registration #1	2010-01-27	6 mi
Registration #2	2013-01-18	34.388 mi
Registration #3	2013-12-19	44.829 mi
Registration #4	2014-12-20	55.329 mi
Registration #5	2014-12-22	55.329 mi
Registration #6	2015-12-22	64.541 mi
Registration #7	2015-12-22	64.541 mi
Registration #8	2016-11-18	73.728 mi
Registration #9	2017-11-24	82.285 mi
Registration #10	2018-11-14	91.219 mi
Registration #11	2019-01-20	91.219 mi
Registration #12	2019-01-20	91.219 mi
Registration #13	2019-01-20	91.219 mi
Registration #14	2019-01-20	91.219 mi
Registration #15	2019-01-20	91.219 mi
Registration #16	2019-01-20	91.219 mi
Registration #17	2019-01-20	91.219 mi
Registration #18	2019-01-20	91.219 mi
Registration #19	2019-01-20	91.219 mi

More info >



Dimensions & weight

Width	1790 mm
Height	1968 mm
Length	3649 mm
Kerb weight	1750 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Number of axles	2
Engine number	100604011809244DT