



General information

Make	FORD
Model	MONDEO GHIA TDCI 140
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



**MOT history**

MOT expiry date	2024-07-02
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	23
Total items failed	12

MOT #18	2023-07-03 12:15
MOT test number	122521915497
Result	✓ Passed
Next expiry date	2024-07-02

MOT #17	2023-06-30 10:59
MOT test number	286743339315
Result	✗ Failed
Advice	Exhaust heatshield loose
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16	2022-06-10 14:28
MOT test number	796575205336
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2022-06-10 14:28**MOT test number** 177637762488**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-06-16 12:47**MOT test number** 437619018566**Result** ✓ Passed**MOT #13** 2020-07-01 11:10**MOT test number** 619537967052**Result** ✓ Passed

**MOT #12**

2020-06-26 10:47

MOT test number

351756991866

Result

✗ Failed

- Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Exhaust system insecure (6.1.2 (a))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

MOT #11

2019-06-17 09:44

MOT test number

898144506588

Result

✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #10

2018-06-15 13:06

MOT test number

915485730181

Result

✓ Passed

- Advice** Nearside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))

**MOT #9** 2017-07-03 12:51**MOT test number** 400075609517**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit on limit (4.1.E.1)**MOT #8** 2016-06-21 11:27**MOT test number** 272513308454**Result** ✓ Passed**MOT #7** 2015-06-17 11:22**MOT test number** 505158465140**Result** ✓ Passed**MOT #6** 2014-07-09 14:02**MOT test number** 869330394157**Result** ✓ Passed**MOT #5** 2014-04-10 10:25**MOT test number** 477780204104**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** O/s/r tyre worn on inside edge**Advice** Offside Front Direction indicators slightly discoloured (1.4.A.2f)**Notice** Nail in offside rear tyre**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/r tyre worn on inside edge



MOT #4	2013-06-26 13:05
MOT test number	339157873121
Result	✓ Passed
MOT #3	2012-07-09 15:30
MOT test number	949061492110
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
MOT #2	2011-09-15 11:36
MOT test number	335068151208
Result	✓ Passed
MOT #1	2010-09-20 11:28
MOT test number	133533060253
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-30
Last registration	2023-07-03
Complete history	See info



Registration #1	2007-09-30	17 mi
Registration #2	2010-09-20	57.502 mi
Registration #3	2011-09-15	75.540 mi
Registration #4	2012-07-09	85.807 mi
Registration #5	2013-06-26	91.587 mi
Registration #6	2014-04-10	152.408 mi
Registration #7	2014-07-09	96.774 mi
Registration #8	2015-06-17	100.092 mi
Registration #9	2016-06-21	102.352 mi
Registration #10	2017-07-03	105.194 mi
Registration #11	2018-06-20	105.207 mi
Registration #12	2019-06-20	105.207 mi
Registration #13	2020-06-20	105.207 mi
Registration #14	2021-06-20	105.207 mi
Registration #15	2022-06-20	105.207 mi
Registration #16	2023-06-20	105.207 mi
Registration #17	2024-06-20	105.207 mi
Registration #18	2025-06-20	105.207 mi
Registration #19	2026-06-20	105.207 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1496 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7J83069