



**BD62FAM**

report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | FIAT           |
| Model               | PUNTO EASY     |
| Colour              | Red            |
| Year of manufacture | -              |
| Top speed           | 97 mph         |
| 0 - 60 mph          | 14.4 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |          |
|-------------------------|----------|
| Power                   | 69 BHP   |
| Cylinders               | 4        |
| Fuel type               | Petrol   |
| Consumption city        | 39.2 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined    | 52.3 mpg |



LABEL UNKNOWN

**MOT history**

|                         |   |
|-------------------------|---|
| <b>MOT #7</b>           | 2019-09-10 13:44  |
| <b>MOT test number</b>  | 958331048195  |
| <b>Result</b>           | ✓ Passed  |
| <b>Next expiry date</b> | 2020-09-09  |
| <b>Advice</b>           | Brake pad(s) wearing thin (1.1.13 (a) (ii))                 |
| <b>Advice</b>           | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #6</b>          | 2018-08-01 13:56 |
| <b>MOT test number</b> | 470712738100     |
| <b>Result</b>          | ✓ Passed         |

|                        |   |
|------------------------|---|
| <b>MOT #5</b>          | 2018-07-30 11:06  |
| <b>MOT test number</b> | 284304505991  |
| <b>Result</b>          | ✗ Failed  |
| <b>Fail</b>            | Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))   |
| <b>Fail</b>            | Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))   |
| <b>Fail</b>            | Windscreen washer provides insufficient washer liquid (3.5 (a))   |
| <b>Fail</b>            | Reversing lamp inoperative (4.6.1 (a))  |
| <b>Fail</b>            | Nearside Front Steering rack has excessive free play detected at the steering wheel (steering rack fitted) inner rack joint (2.3 (a) (i)) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #4</b>          | 2017-08-17 11:21 |
| <b>MOT test number</b> | 581292528488     |
| <b>Result</b>          | ✓ Passed         |

|                        |  |
|------------------------|--|
| <b>MOT #3</b>          | 2016-07-27 08:49                                       |
| <b>MOT test number</b> | 716744074895   |
| <b>Result</b>          | ✓ Passed   |
| <b>Advice</b>          | Parking brake lever has little reserve travel (3.1.6b) |



|                         |   |
|-------------------------|---|
| MOT #2                  | 2016-07-27 08:49  |
| MOT test number         | 912428222996  |
| Result                  | ✗ Failed  |
| Pass with rectification | Windscreen washer provides insufficient washer liquid (8.2.3) |
| Advice                  | Parking brake lever has little reserve travel (3.1.6b)        |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2015-08-19 09:07 |
| MOT test number | 899211635284     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FIAT had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>BD62FAM</b> |
| Plate since          | 2019-09-29     |
| Current registration | <b>BD62FAM</b> |
| Plate since          | 2019-09-29     |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 8                        |
| First mileage registration | 2012-11-20               |
| Last registration          | 2019-09-10               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2012-11-20 | 25 mi     |
| Registration #2 | 2015-08-19 | 18.374 mi |
| Registration #3 | 2016-07-27 | 36.443 mi |
| Registration #4 | 2016-07-27 | 36.443 mi |
| Registration #5 | 2019-09-10 | 36.443 mi |
| Registration #6 | 2019-09-10 | 36.443 mi |
| Registration #7 | 2019-09-10 | 36.443 mi |
| Registration #8 | 2019-09-10 | 36.443 mi |

More info >





Car features

The FIAT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1687 mm |
| Height              | 1490 mm |
| Length              | 4065 mm |
| Wheel base          | 2510 mm |
| Kerb weight         | 1030 kg |
| Max. allowed weight | 1590 kg |

Additional information

|                 |                       |
|-----------------|-----------------------|
| Fuel delivery   | Multi-Point Injection |
| Number of doors | 5                     |
| Number of seats | 5                     |

Engine number 0207966