



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Black
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-07
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-22
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	13
Total items failed	11

MOT #16	2023-10-23 17:26
MOT test number	830533348573
Result	✓ Passed
Next expiry date	2024-10-22
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-10-13 15:41
MOT test number	546561817162
Result	✗ Failed
Advice	Front Tyre worn close to legal limit/worn on edge Both tread wear (5.2.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Exhaust has a major leak of exhaust gases Between centre and tail (6.1.2 (a))
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #14**

2022-08-11 15:33

MOT test number

521351641325

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13**

2022-08-10 11:19

MOT test number

224544849145

Result

✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12**

2021-08-12 13:05

MOT test number

267800188804

Result

✓ Passed

MOT #11

2021-08-12 11:13

MOT test number

416527315943

Result

✗ Failed

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2021-01-08 12:22**MOT test number** 893888932125**Result** ✓ Passed**MOT #9** 2020-01-02 10:24**MOT test number** 476396535345**Result** ✓ Passed**MOT #8** 2018-12-28 10:31**MOT test number** 206776989844**Result** ✓ Passed**MOT #7** 2018-12-28 10:31**MOT test number** 418023982551**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper not working (3.4 (a))**Pass with rectification** Offside Front Windscreen wiper not working (3.4 (a))**MOT #6** 2018-01-08 08:52**MOT test number** 296864118191**Result** ✓ Passed**MOT #5** 2017-06-26 14:58**MOT test number** 778897747275**Result** ✓ Passed**MOT #4** 2016-07-26 09:18**MOT test number** 125594554471**Result** ✓ Passed**Advice** Offside rear tyre cracking on tread



MOT #3	2015-07-29 10:32
MOT test number	286810615223
Result	✓ Passed
<div>NoticeOff side rear tyre cracking</div>	

MOT #2	2014-07-25 12:08
MOT test number	825696404237
Result	✓ Passed

MOT #1	2013-07-29 11:35
MOT test number	858750913222
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	22 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2015-01-01
Current registration	 VAUXH
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-07-30
Last registration	2023-10-23
Complete history	See info



Registration #1	2010-07-30	26 mi
Registration #2	2013-07-29	27.465 mi
Registration #3	2014-07-25	34.431 mi
Registration #4	2015-07-29	39.464 mi
Registration #5	2016-07-26	44.076 mi
Registration #6	2017-06-26	45.041 mi
Registration #7	2018-01-08	45.362 mi
Registration #8	2018-12-28	50.782 mi
Registration #9	2018-12-28	50.782 mi
Registration #10	2019-05-29	51.377 mi
Registration #11	2019-05-29	51.377 mi
Registration #12	2019-05-29	51.377 mi
Registration #13	2019-05-29	51.377 mi
Registration #14	2019-05-29	51.377 mi
Registration #15	2019-05-29	51.377 mi
Registration #16	2019-05-29	51.377 mi
Registration #17	2019-05-29	51.377 mi
Registration #18	2019-05-29	51.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1226589