




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CC MATCH EDITION TDI BMT
Colour	Silver
Year of manufacture	2016
Top speed	123 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D





## Internet history

### Entry 2

Date	2024-02-22
Pictures	42
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 1

Date	2021-12-01
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2025-04-01
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	6
Total items failed	3

MOT #7	2024-04-02 15:49
MOT test number	846001120659
Result	✓ Passed
Next expiry date	2025-04-01

MOT #6	2023-05-23 11:57
MOT test number	280254550607
Result	✓ Passed

MOT #5	2022-05-27 08:41
MOT test number	108257100167
Result	✓ Passed

MOT #4	2021-06-03 15:41
MOT test number	578234930133
Result	✓ Passed
Advice	Offside Rear Wearing out of shape on inner edge

**MOT #3** 2021-06-02 12:40**MOT test number** 184279528060**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Wearing out of shape on inner edge**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**MOT #2** 2020-06-03 09:00**MOT test number** 279434951134**Result** ✓ Passed**MOT #1** 2019-06-05 13:47**MOT test number** 224342397875**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
1 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	1 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-08
Last registration	2024-04-02
Complete history	<a href="#">See info</a>



Registration #1	2016-07-08	12 mi
Registration #2	2019-06-05	35.903 mi
Registration #3	2020-06-03	41.502 mi
Registration #4	2021-06-02	45.278 mi
Registration #5	2021-06-03	45.280 mi
Registration #6	2022-06-02	45.277 mi
Registration #7	2022-06-02	45.277 mi
Registration #8	2022-06-02	45.277 mi
Registration #9	2022-06-02	45.277 mi
Registration #10	2022-06-02	45.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1703 mm
Length	4426 mm
Wheel base	2604 mm
Kerb weight	1597 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CUVC471017