





report date: 2024-03-29

General information

Make	RENAULT
Model	CAPTUR DYNAMIQUE S NAV TCE
Colour	Orange
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	140 Nm at 2.250 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2023-01-02

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-02-04
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-09
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #9		2023-10-31 12:46
MOT test	number	916565532631
Result		✓ Passed
Next expi	y date	2024-11-09
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2022-10-31 17:00
MOT test number	876995753135
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2022-10-31 10:34
MOT test number	926749988693
Result	× Failed
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2021-11-08 16:02
MOT test number	839066312561
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2021-11-08 11:40

MOT test number 576485205808

Result X Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Direction indicator not working (4.4.1 (a) (ii))

MOT #4 2020-11-10 12:08

MOT test number 697636604621

Result ✓ Passed

MOT #3 2020-03-09 14:23

MOT test number 503685228470

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #2 2019-03-07 11:15

MOT test number 397087814540

Result ✓ Passed

MOT #1 2018-03-05 14:45

MOT test number 953236204507

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/11



HY150UH report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

HY150UH

report date: 2024-03-29

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this RENAULT had different number plates.

***The company of the company of

More info >

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-13
Last registration	2023-10-31
Complete history	See info



Registration #1	2015-03-13	25 mi
Registration #2	2018-03-05	20.358 mi
Registration #3	2019-03-07	30.225 mi
Registration #4	2020-03-09	39.892 mi
Registration #5	2020-11-10	44.905 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71,777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1109 kg
Max. allowed weight	1656 kg

Additional information

Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Engine number

D011002