



NDI2ZWJ

report date: 2024-03-29

General information

Make	SUZUKI
Model	GRAND VITARA DDIS
Colour	Grey
Year of manufacture	2012
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-19
Pictures	44
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-10
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	21
Total items failed	3

MOT #10	2023-06-08 11:07
---------	------------------

MOT test number	196331260502
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-10
------------------	------------

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front top mount creaking
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front top mount creaking
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #9**

2023-06-06 10:36

MOT test number

925436534436

Result**✗ Failed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front top mount creaking
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front top mount creaking
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Front Headlamp aim too low (4.1.2 (a))

MOT #8

2022-06-06 11:09

MOT test number

591976654435

Result**✓ Passed**

- Advice** Rear exhaust heat shield insecure
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both discs corroded (1.1.14 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7

2021-06-11 08:15

MOT test number

301411435864

Result**✓ Passed**



MOT #6	2020-12-01 14:35
---------------	------------------

MOT test number	513149382136
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2019-06-13 14:39
---------------	------------------

MOT test number	528089726890
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2018-06-11 10:40
---------------	------------------

MOT test number	405078706687
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2017-06-26 10:57
---------------	------------------

MOT test number	749488289535
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2016-06-06 13:52
---------------	------------------

MOT test number	433853552518
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2015-06-09 16:07
---------------	------------------

MOT test number	418870565169
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
10 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	ND12ZWJ
Plate since	2024-03-29
Current registration	ND12ZWJ
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-06-27
Last registration	2023-06-08
Complete history	See info



Registration #1	2012-06-27	22 mi
Registration #2	2015-06-09	50.263 mi
Registration #3	2016-06-06	56.877 mi
Registration #4	2017-06-26	63.477 mi
Registration #5	2018-06-11	69.623 mi
Registration #6	2019-06-13	79.162 mi
Registration #7	2020-06-08	85.212 mi
Registration #8	2021-06-08	91.262 mi
Registration #9	2022-06-08	97.312 mi
Registration #10	2023-06-08	103.362 mi
Registration #11	2024-03-29	109.412 mi
Registration #12	2024-03-29	115.462 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1695 mm
Length	4300 mm
Wheel base	2640 mm
Kerb weight	1680 kg
Max. allowed weight	2170 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	F9QC-019703