





report date: 2024-03-29

## General information

Make	AUDI
Model	Q5 TDI QUATTRO S LINE PLUS
Colour	Blue
Year of manufacture	2015
Top speed	130 mph
0 - 100 km/h	8.4 seconds
0 - 60 mph	8.4 seconds
Gearbox	7 speed Semi-Automatic

## Engine & fuel consumption

Power	140 kW / 191 HP / 187 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	47.1 mpg
CO2 emission	157 g/km
CO2 label	G




CarCheck.co.uk page 1/12



## Internet history

## Entry 1

Date	2021-01-28
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



2023-03-20 13:01

**MOT** history

MOT #7

MOT expiry date	2025-03-21
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	18
Total items failed	1

MOT #9	2024-03-18 13:28
MOT test number	592727109200
Result	✓ Passed
Next expiry date	2025-03-21
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2024-03-18 13:28
MOT test number		973703768710
Result		🗙 Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Advice Offside Rear Tyr	re worn close to legal limit/worn on edge (5.2.3 (e))	

number	825693028272
	✓ Passed
	2022-03-17 16:02
number	964133301246
	✓ Passed
Offside Front Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))  Nearside Front Tyre worn close to legal limit/worn on edge on 1.6 mm (5.2.3 (e))	
	number  Offside Front Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))

CarCheck.co.uk page 3/12



Result

YB15UXT report date: 2024-03-29

× Failed

**MOT #5** 2022-03-17 11:43

MOT test number 776441054806

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

**Advice** Nearside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge on 1.6 mm (5.2.3 (e))

**Advice** TPMS light on dash

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))

**DANGEROUS** Road wheel more than one fixing missing all 4 wheels missing a bolt (5.2.1 (a) (ii))

MOT #4 2021-03-22 10:27

**MOT test number** 721081340503

Result \( \sqrt{Passed} \)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #3 2020-03-07 12:59

**MOT test number** 433230750454

**Result** ✓ Passed

**MOT #2** 2019-03-11 10:07

**MOT test number** 620532235129

**Result** ✓ Passed

CarCheck.co.uk page 4/12



YB15UXT

report date: 2024-03-29

MOT #1		2018-06-15 12:28
MOT test	number	849547897995
Result		✓ Passed
Advice	Engine cover and under trays fitted obscuring view of some components.	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	21 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-


CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



## Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



## Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-22
Last registration	2024-03-18
Complete history	See info



Registration #1	2015-06-22	17 mi
Registration #2	2018-06-15	72.363 mi
Registration #3	2019-03-11	84.924 mi
Registration #4	2020-03-07	98.808 mi
Registration #5		11.777 es
Registration #6	2021-03-22	111.538 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

## Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	32%
Safety systems	71%
Overall rating	76%
Video	see crash video



## Dimensions & weight

Width	1898 mm
Height	1655 mm
Length	4629 mm
Wheel base	2807 mm
Kerb weight	1860 kg
Max. allowed weight	2470 kg

# Additional information

Fuel tank capacity	75
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number CNHA172332