



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D SPORT S40
Colour	Grey
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #7	2019-10-24 14:33
MOT test number	711738657667
Result	✓ Passed
Next expiry date	2020-10-23

MOT #6	2019-10-24 10:18
MOT test number	783560054125
Result	✗ Failed
Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #5	2018-09-20 14:11
MOT test number	714138244800
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

**MOT #4** 2018-09-18 10:38**MOT test number** 868760787508**Result** ✗ Failed**Advice** Rear Exhaust mounting defective hanger burst (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Position lamps both o/s and n/s have a bulb inoperative.**Fail** Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Tyre size on front different size fitted to rear axle.**Fail** Dipswitch does not operate immediately when selected on main beam (4.1.3 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #3** 2017-10-03 13:08**MOT test number** 166084785810**Result** ✓ Passed



MOT #2	2017-10-02 09:42
MOT test number	109721758396
Result	✗ Failed
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)
Fail	Exhaust has a major leak of exhaust gases (7.1.2)
Fail	Offside Rear Brake cable has wires broken and is significantly weakened (3.5.1b)
Fail	Offside Rear rear parking brake recording little or no effort (3.7.B.6a)

MOT #1	2016-04-14 09:15
MOT test number	947165571155
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2005-03-09
Last registration	2019-10-24
Complete history	See info



Registration #1	2005-03-09	20 mi
Registration #2	2016-04-14	104.322 mi
Registration #3	2017-10-02	117.935 mi
Registration #4	2017-10-03	117.935 mi
Registration #5	2019-10-24	117.935 mi
Registration #6	2019-10-24	117.935 mi
Registration #7	2019-10-24	117.935 mi
Registration #8	2019-10-24	117.935 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

4002000