



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | VOLVO |
| Model | V70 D5 SE LUX |
| Colour | Grey |
| Year of manufacture | 2013 |
| Top speed | 137 mph |
| 0 - 60 mph | 7.5 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 212 BHP |
| Max. torque | 420 Nm at 1.500 rpm |
| Engine capacity | 2.400 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 164 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-08 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-01-05 |
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 3 |

| | |
|-------------------------|---|
| MOT #11 | 2024-01-06 12:41 |
| MOT test number | 246598756284 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-05 |
| Advice | Rear Coil spring corroded (5.3.1 (b) (i)) |

| | |
|------------------------|---|
| MOT #10 | 2023-04-20 10:50 |
| MOT test number | 622874980976 |
| Result | ✓ Passed |
| Advice | Power steering pipe/hose has slight seepage (2.1.5 (a)) |

| | |
|------------------------|--|
| MOT #9 | 2022-08-24 12:59 |
| MOT test number | 703305272274 |
| Result | ✓ Passed |
| Advice | Tyre worn close to legal limit/worn on edge Both Front (5.2.3 (e)) |

| | |
|------------------------|---|
| MOT #8 | 2021-08-24 13:34 |
| MOT test number | 647823613600 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e)) |

**MOT #7** 2021-08-24 13:34**MOT test number** 792673823045**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #6** 2020-08-12 10:04**MOT test number** 183687237962**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin both rear (1.1.13 (a) (ii))**MOT #5** 2019-07-23 08:22**MOT test number** 520430472430**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Central Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**MOT #4** 2018-07-24 08:27**MOT test number** 736329093729**Result** ✓ Passed**Advice** Offside Lower Power steering pipe/hose has slight seepage (2.1.5 (a))**MOT #3** 2017-08-03 08:17**MOT test number** 270232086651**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #2 | 2016-07-28 15:10 |
| MOT test number | 329518387105 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2016-07-28 10:28 |
| MOT test number | 653567356255 |
| Result | ✗ Failed |

- Fail

Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
5 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 279 |
| MOT expiry date | 5 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2013-08-27 |
| Last registration | 2024-01-06 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2013-08-27 | 20 mi |
| Registration #2 | 2016-07-28 | 66.829 mi |
| Registration #3 | 2016-07-28 | 66.830 mi |
| Registration #4 | 2017-08-03 | 87.671 mi |
| Registration #5 | 2018-07-24 | 106.560 mi |
| Registration #6 | 2019-07-23 | 124.388 mi |
| Registration #7 | 2020-08-12 | 140.770 mi |
| Registration #8 | 2021-08-12 | 157.152 mi |
| Registration #9 | 2022-08-12 | 173.534 mi |
| Registration #10 | 2023-08-12 | 189.916 mi |
| Registration #11 | 2024-01-06 | 206.298 mi |
| Registration #12 | 2024-01-06 | 222.680 mi |
| Registration #13 | 2024-01-06 | 239.062 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 88% |
| Children | 84% |
| Pedestrian | 43% |
| Safety systems | 71% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1861 mm |
| Height | 1547 mm |
| Length | 4823 mm |
| Wheel base | 2816 mm |
| Kerb weight | 1769 kg |
| Max. allowed weight | 2310 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|---------|
| Number of axles | 2 |
| Engine number | 1390004 |