





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Black
Year of manufacture	-
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-28

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT #18 2023-06-10 15:28

MOT test number 120254556336

Result ✓ Passed

Next expiry date 2024-06-09

Advice Nearside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #17 2023-06-10 14:54

MOT test number 841024751150

Result X Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #16 2021-10-18 16:13

MOT test number 827465537694

Advice Offside Front Inner Play in steering rack inner joint(s)

Advice Nearside Front Inner Play in steering rack inner joint(s)

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #15 2020-11-10 16:44 **MOT test number** 757613636398 Result ✓ Passed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Nearside Front steering rack inner joint has slight play Advice Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Bottom cover fitted Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2020-11-10 10:49
MOT test number	881942227038
Result	× Failed
Advice Nearside Front steering rack inner joint has slight play	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))	
Advice Bottom cover fitted	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c	z))
Fail Nearside Rear Outer Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2	(c))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #13 2019-11-01 13:27 **MOT test number** 568788121592 Result ✓ Passed Advice Oil leak, but not excessive (8.4.1 (a) (i)) Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii)) Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i)) Advice Advice Under-tray fitted Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2018-11-13 11:25
MOT test	number 649617500457
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 5/14



report date: 2024-03-29

2018-11-13 11:25 **MOT #11** 231417704805 **MOT** test number Result × Failed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Pass with rectification Offside Front Position lamp not working (4.2.1 (a)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10		2017-09-27 15:13
MOT test	number	865757617103
Result		✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)
Advice	Both inner steering joints have play	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3	.5.1i)

CarCheck.co.uk page 6/14



report date: 2024-03-29

2017-08-29 09:23 **MOT #9** 962694755669 **MOT** test number Result × Failed Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3) Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f) Fail Nearside Rear Stop lamp not working (1.2.1b) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Nearside Front Headlamp not working on dipped beam (1.7.5a) Fail Advice Both inner steering joints have play Offside Rear Direction indicator incorrect colour (1.4.A.2f) Fail Fail Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #8	2016-08-26 09:58
MOT test number	931335739928
Result	✓ Passed

MOT #7	2015-07-31 17:09
MOT test number	808282015293
Result	✓ Passed
Advice Front Direction indicators slightly discoloured (1.4.A.2f)	

MOT #6	2014-08-01 13:21
MOT test number	119743514212
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #5	2014-08-01 10:42
MOT test number	657323914240
Result	× Failed
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Notice Advise new headlamp bulbs	
Fail Nearside Headlamp aim too low (1.8)	
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Fail Offside Registration plate lamp not working (1.1.C.1d)	

MOT #4		2013-07-12 10:52
MOT test i	number	218993993195
Result		✓ Passed
Notice	Small lip on front disc	
Notice	Front pads 80 to 90% worn	

MOT #3	2012-07-19 09:12
MOT test number	395181702297
Result	✓ Passed
MOT #2	2011-07-20 12:18
MOT test number	877811101235
Result	✓ Passed

CarCheck.co.uk page 8/14



report date: 2024-03-29

MOT #1 2010-07-28 10:56
MOT test number 240619200208

Notice Nail in nearside rear tyre

Notice Slight buckle in n/s/r wheel inner side

CarCheck.co.uk page 9/14



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NE N
Plate since	
	More info

CarCheck.co.uk page 11/14



YNO7VPV report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-08-01
Last registration	2023-06-10
Complete history	See info



Registration #1	2007-08-01	11 mi
Registration #2	2010-07-28	18.882 mi
Registration #3	2011-07-20	23.976 mi
Registration #4	2012-07-19	30.585 mi
Registration #5	2013-07-12	39.156 mi
Registration #6	2014-08-01	52.353 mi
Registration #7	2014-08-01	52.357 mi
Registration #8	2015-07-31	68.554 mi
Registration #9	2016-08-26	82.932 mi
Registration #10	2017-08-29	90.779 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm

Additional information

Number of seats	4
Number of axles	2
Engine number	NOT KNOWN

CarCheck.co.uk page 14/14