



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Black
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 2

Date 2023-12-17

Pictures 8

Listing price [View report](#)





source: cargurus.co.uk

Entry 1

Date 2021-12-24

Pictures 54

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-08
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	38
Total items failed	6

MOT #15	2024-04-09 13:44
MOT test number	274794658846
Result	✓ Passed
Next expiry date	2025-04-08
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #14	2024-04-09 08:46
MOT test number	520536022582
Result	✗ Failed
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #13	2023-12-28 12:37
MOT test number	321200156431
Result	✓ Passed

**MOT #12**

2023-09-09 09:43

MOT test number

736026013750

Result

✓ Passed

Advice Integral body structure is corroded but structural rigidity is not significantly reduced light general underside age related surface corrosion (6.1.1 (c) (i))

Advice Under trays and covers fitted masking some testable items

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement slight play in front d-bushes (5.3.4 (a) (i))

Advice Coil spring corroded all springs (5.3.1 (b) (i))

MOT #11

2022-09-09 08:01

MOT test number

711008201495

Result

✓ Passed

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edges (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Coil spring corroded All four coil springs (5.3.1 (b) (i))

Advice Covers fitted masking some testable items

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edges (5.2.3 (e))

Advice Hand brake travel long but has reserve

MOT #10

2021-09-10 12:31

MOT test number

631191304938

Result

✓ Passed

**MOT #9** 2018-03-23 16:17**MOT test number** 226778272869**Result** ✓ Passed**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-03-14 09:11**MOT test number** 353476734408**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit Inside Edge (4.1.E.1)**MOT #7** 2017-03-13 13:10**MOT test number** 189356331638**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit Inside Edge (4.1.E.1)**Fail** Front brake disc in such a condition that it is seriously weakened Both (3.5.1i)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2016-03-04 09:48**MOT test number** 838225294418**Result** ✓ Passed**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #5**

2016-03-04 09:48

MOT test number

629218798589

Result

✗ Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4**

2015-04-14 14:51

MOT test number

527764805181

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside front tyre worn on outer edge**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Centre Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3**

2015-03-31 17:02

MOT test number

968560295011

Result

✗ Failed

Notice Advise front tyres worn on edges**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside rear parking (secondary) brakes imbalanced (3.7.B.6b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-03-06 13:41
MOT test number	806665264090
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-03-08 14:07
MOT test number	725117263073
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-08
Last registration	2024-04-09
Complete history	See info



Registration #1	2010-03-08	12 mi
Registration #2	2013-03-08	25.903 mi
Registration #3	2014-03-06	42.509 mi
Registration #4	2015-03-31	53.425 mi
Registration #5	2015-04-14	53.478 mi
Registration #6	2016-03-04	67.254 mi
Registration #7	2016-03-04	67.254 mi
Registration #8	2017-03-13	79.249 mi
Registration #9	2017-03-14	79.267 mi
Registration #10	2018-03-08	91.254 mi
Registration #11	2018-03-08	91.254 mi
Registration #12	2018-03-08	91.254 mi
Registration #13	2018-03-08	91.254 mi
Registration #14	2018-03-08	91.254 mi
Registration #15	2018-03-08	91.254 mi
Registration #16	2018-03-08	91.254 mi
Registration #17	2018-03-08	91.254 mi
Registration #18	2018-03-08	91.254 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBA626086