





report date: 2024-03-29

#### General information

Make	MINI
Model	ONE
Colour	Blue
Year of manufacture	2013
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2021-06-11


Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-25
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	11
Total items failed	9

MOT #12	2023-06-26 15:05
MOT test number	585849208311
Result	<b>✓</b> Passed
Next expiry date	2024-06-25
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11		2022-06-21 09:52
MOT test i	number	743351654844
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing dated 15 (5.2.3 (d) (ii))	

MOT #10	2021-06-11 10:04
MOT test number	986500361235
Result	✓ Passed

MOT #9	2019-12-20 14:42
MOT test number	943752410805
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #8 2019-12-20 14:42

**MOT test number** 181696291948

**Result** X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2

(c))

MOT #7 2018-12-17 17:27

**MOT test number** 464340538355

Result 

Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2018-06-02 16:01

**MOT test number** 982276284705

MOT #5 2018-06-02 16:01

**MOT test number** 385753759347

Result X Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4 2017-06-03 12:55

**MOT test number** 379146256924

**Advice** Nearside Rear Tyre worn close to the legal limit worn outer edge (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit worn inner edge (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit worn outer edge (4.1.E.1)

CarCheck.co.uk page 4/12



MOT test number
668897905259

Result
Advice Offside Rear Tyre worn close to the legal limit worn outer edge (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm outer edge (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit worn outer edge (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit worn inner edge (4.1.E.1)

MOT #2 2016-05-17 15:11 **MOT** test number 110313535398 Result ✓ Passed 2016-05-16 09:06 **MOT #1 MOT** test number 787167791980 Result × Failed Fail Offside Front Valve stem seriously damaged (4.1.D.1e) Fail Offside Rear Valve stem seriously damaged (4.1.D.1e) Fail Nearside Front Valve stem seriously damaged (4.1.D.1e) Nearside Rear Valve stem seriously damaged (4.1.D.1e) Fail Fail Offside Front brake disc in such a condition that it is seriously weakened split around collar (3.5.1i)

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	D
	-
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
MARKET STATE OF THE STATE OF TH	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-14
Last registration	2023-06-26
Complete history	See info



Registration #1	2013-03-14	7 mi
Registration #2	2016-05-16	17.099 mi
Registration #3	2016-05-17	17.099 mi
Registration #4	2017-06-03	24.430 mi
Registration #5	2017-06-03	24.431 mi
Registration #6	2018-06-02	29.228 mi
Registration #7	2018-06-02	29.228 mi
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

# Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number A474J474