



report date: 2024-03-29

General information

Make	LAND ROVER
Model	FREELANDER TD4 GS
Colour	Black
Year of manufacture	2014
Top speed	112 mph
0 - 100 km/h	11.7 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 150 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-06-26
Pictures	45
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-04
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	16
Total items failed	3

MOT #10	2023-06-13 08:04
MOT test number	393350180251
Result	✓ Passed
Next expiry date	2024-07-04

MOT #9	2022-06-14 10:37
MOT test number	521205574335
Result	✓ Passed
Advice	Rear Exhaust heat shield insecure
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2022-06-14 10:37
MOT test number	622097217905
Result	✗ Failed
Pass with rectification	Offside Rear Brake pad(s) less than 1.5 mm thick Both pads (1.1.13 (a) (ii))
Advice	Rear Exhaust heat shield insecure
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7	2021-07-05 15:35
MOT test number	886379406856
Result	✓ Passed



MOT #6	2020-06-17 13:58
MOT test number	617272041307
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2020-06-16 08:02
MOT test number	666260702809
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #4	2019-05-14 08:23
MOT test number	215708338140
Result	✓ Passed
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2019-05-14 08:23
MOT test number	702696383529
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2018-05-15 14:09
MOT test number	798281931233
Result	✓ Passed

MOT #1	2017-09-20 08:26
MOT test number	812193845021
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
4 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	SY64UVU
Plate since	2019-09-29
Current registration	SY64UVU
Plate since	2019-09-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2023-06-13
Complete history	See info



Registration #1	2014-09-30	17 mi
Registration #2	2017-09-20	45.273 mi
Registration #3	2018-05-15	51.933 mi
Registration #4	2019-05-14	59.956 mi
Registration #5	2019-05-14	59.956 mi
Registration #6	2020-06-16	67.225 mi
Registration #7	2020-06-16	67.225 mi
Registration #8	2020-06-16	67.225 mi
Registration #9	2020-06-16	67.225 mi
Registration #10	2020-06-16	67.225 mi
Registration #11	2020-06-16	67.225 mi
Registration #12	2020-06-16	67.225 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1735 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ794075741224DT