




report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Orange
Year of manufacture	2006
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	194 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-01-21
Pictures	3
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-04-09
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	66
Total items failed	7

MOT #20	2024-04-10 09:22
MOT test number	312918504401
Result	✓ Passed
Next expiry date	2025-04-09
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Tyre slightly damaged/cracking or perishing Both rears (5.2.3 (d) (ii))
Advice	Offside Power steering component has slight seepage from a component Rack (2.1.5 (a))

MOT #19	2022-11-02 11:23
MOT test number	908217851467
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18** 2021-11-11 09:08**MOT test number** 412392436563**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Headlamp has a product on the lens but not seriously reducing light output both lamps (4.1.4 (b))**Advice** Offside Rear Road wheel slightly distorted inner bead rim (5.2.2 (c) (i))**MOT #17** 2020-11-24 09:32**MOT test number** 798247171204**Result** ✓ Passed**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #16** 2020-11-24 09:32**MOT test number** 325510936918**Result** ✗ Failed**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))



MOT #15	2019-06-24 16:41
MOT test number	424944409118
Result	✓ Passed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
Advice	Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))

MOT #14	2019-06-24 08:46
MOT test number	376028827157
Result	✗ Failed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
Fail	Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))
Advice	O/s front inner c/v boot split
Fail	Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

MOT #13	2018-07-09 11:00
MOT test number	898945141623
Result	✓ Passed
Advice	Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))
Advice	O/s front inner c/v boot split
Advice	Front Tyre slightly damaged/cracking or perishing both sides 205/55/16 (5.2.3 (d) (i))
Advice	Wipers starting to smear

**MOT #12**

2017-07-04 16:39

MOT test number

400993003079

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Wear inner edge o/s front tyre 205/55/16
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Headlamp has a product on the lens but not seriously reducing light output both sides (poor condition) (1.7.5a)
- Advice** O/s inner c/v boot split
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Wipers starting to smear

MOT #11

2017-07-04 09:18

MOT test number

704727097278

Result

✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** O/s inner c/v boot split
- Advice** Wipers starting to smear
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Wear inner edge o/s front tyre 205/55/16
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Headlamp has a product on the lens but not seriously reducing light output both sides (poor condition) (1.7.5a)

**MOT #10** 2016-06-21 08:36**MOT test number** 666255995533**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Wipers starting to smear
- Advice** Headlamp has a product on the lens but not seriously reducing light output both sides (1.7.5a)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** O/s inner c/v boot leaking

MOT #9 2015-07-06 09:31**MOT test number** 268417685148**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #8 2015-07-06 09:31**MOT test number** 927857985103**Result** ✗ Failed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #7** 2014-06-27 09:32**MOT test number** 269788674119**Result** ✓ Passed**Notice** Nail in nearside front tyre**Advice** Nearside Inner Front Road wheel slightly damaged (4.2.A.1a)**Notice** Both rear tyres starting to perish 205/55/16**Notice** Nail in nearside rear tyre**MOT #6** 2013-06-24 09:21**MOT test number** 777105273175**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #5** 2013-06-24 09:21**MOT test number** 157235073111**Result** ✗ Failed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #4** 2012-06-21 12:36**MOT test number** 686993272170**Result** ✓ Passed**Notice** Coolant leak**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Vehicle's internal headlight adjuster altered to recheck lights

**MOT #3** 2011-06-22 09:02**MOT test number** 275543371197**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside front tyre bald inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-06-22 09:19**MOT test number** 221663270177**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-07-01 10:44**MOT test number** 921252289192**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	9 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-07-20
Last registration	2024-04-10
Complete history	See info



Registration #1	2006-07-20	25 mi
Registration #2	2009-07-01	12.215 mi
Registration #3	2010-06-22	20.326 mi
Registration #4	2011-06-22	27.020 mi
Registration #5	2012-06-21	33.051 mi
Registration #6	2013-06-24	39.063 mi
Registration #7	2014-06-27	43.436 mi
Registration #8	2015-07-06	47.968 mi
Registration #9	2016-06-21	53.100 mi
Registration #10	2017-07-04	59.254 mi
Registration #11	2018-06-20	65.377 mi
Registration #12	2019-06-20	71.500 mi
Registration #13	2020-06-20	77.623 mi
Registration #14	2021-06-20	83.746 mi
Registration #15	2022-06-20	89.869 mi
Registration #16	2023-06-20	95.992 mi
Registration #17	2024-06-20	102.115 mi
Registration #18	2025-06-20	108.238 mi
Registration #19	2026-06-20	114.361 mi
Registration #20	2027-06-20	120.484 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1420 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	6B85854
---------------	---------