



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	A-CLASS A170 ELEGANCE SE
Colour	Red
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	11.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #20</b>	2021-11-11 12:48
<b>MOT test number</b>	917037602227
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-11-10

<b>MOT #19</b>	2020-10-23 16:33
<b>MOT test number</b>	634033032840
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Play in steering rack inner joint(s)

<b>MOT #18</b>	2020-10-23 11:08
<b>MOT test number</b>	929901911032
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Fail</b>	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Offside Play in steering rack inner joint(s)

<b>MOT #17</b>	2019-10-21 13:25
<b>MOT test number</b>	479348362486
<b>Result</b>	✓ Passed
<b>Advice</b>	Play in steering rack inner joint(s)

<b>MOT #16</b>	2019-10-18 08:25
<b>MOT test number</b>	409919829463
<b>Result</b>	✗ Failed
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Advice</b>	Play in steering rack inner joint(s)

**MOT #15** 2018-10-09 15:33**MOT test number** 587396333890**Result** ✓ Passed**MOT #14** 2018-10-09 10:21**MOT test number** 418044945012**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #13** 2017-10-05 11:18**MOT test number** 387095263980**Result** ✓ Passed**MOT #12** 2017-10-05 10:05**MOT test number** 902018592745**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #11** 2016-10-05 13:45**MOT test number** 638253225673**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front tyres worn on edges.

**MOT #10** 2015-10-30 11:07**MOT test number** 916121850739**Result** ✓ Passed**Advice** Offside Rear nail in tyre**MOT #9** 2015-10-30 11:07**MOT test number** 977079342725**Result** ✗ Failed**Advice** Offside Rear nail in tyre**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #8** 2014-10-29 13:37**MOT test number** 637112404374**Result** ✓ Passed**Notice** Rear wiper blade split**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2013-10-24 11:19**MOT test number** 695317193251**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-10-24 11:19**MOT test number** 379567693223**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp aim too high (1.8)

**MOT #5** 2012-10-19 13:03**MOT test number** 315233192470**Result** ✓ Passed**MOT #4** 2011-09-02 13:25**MOT test number** 608495041210**Result** ✓ Passed**Notice** Rear wiper split.**MOT #3** 2011-09-02 13:25**MOT test number** 319345641297**Result** ✗ Failed**Notice** Rear wiper split.**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #2** 2010-09-04 10:57**MOT test number** 361727040279**Result** ✓ Passed**MOT #1** 2009-09-07 13:43**MOT test number** 772080759274**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From
Owner	From
Owner	From
Owner	From
Owner	From
Owner	From

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>VO56AFE</b>
Plate since	2019-03-29
Current registration	 <b>VO56AFE</b>
Plate since	2019-03-29

More info >





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-09-23
Last registration	2021-11-11
Complete history	<a href="#">See info</a>



Registration #1	2006-09-23	10 mi
Registration #2	2009-09-07	10.518 mi
Registration #3	2010-09-04	14.139 mi
Registration #4	2011-09-02	17.244 mi
Registration #5	2012-10-19	21.968 mi
Registration #6	2013-10-24	27.063 mi
Registration #7	2014-10-29	31.932 mi
Registration #8	2016-10-05	44.086 mi
Registration #9	2017-10-05	54.505 mi
Registration #10	2019-05-20	55.377 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi
Registration #16	2019-05-20	55.377 mi
Registration #17	2019-05-20	55.377 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1764 mm
Height	1593 mm
Length	3838 mm
Wheel base	2568 mm
Kerb weight	1210 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	26694030271287