





report date: 2024-03-29

### General information

Make	FIAT
Model	PUNTO EVO GP
Colour	Red
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/13



## Internet history

#### Entry 2

Date 2021-07-17	
-----------------	--


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

Date	2021-01-29	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-12-19
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #15	2023-12-07 10:08
MOT test number	387141441188
Result	<b>✓</b> Passed
Next expiry date	2024-12-19
Advice Rear exhaust corroded	

MOT #14	2022-12-02 16:13
MOT test number	106422466005
Result	✓ Passed
Advice Nearside Rear tyre perished	
Advice Offside Rear tyre perished	

MOT #13	2021-12-20 11:02
MOT test number	806050542194
Result	<b>√</b> Passed

CarCheck.co.uk page 3/13



MOT #12 2021-12-20 11:02

**MOT test number** 168806361724

Result × Failed

Pass with rectification Parking brake lever has excessive movement indicating incorrect adjustment

(1.1.6(c))

**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #11** 2020-12-18 12:41

**MOT test number** 596317292909

**Result** ✓ Passed

**MOT #10** 2020-12-17 12:02

**MOT test number** 735289529729

**Result** ★ Failed

MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #9 2019-11-27 15:16

MOT test number 819112197490

**Advice** Rear coil springs corroded

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Rear exhaust silencer corroded

CarCheck.co.uk page 4/13



MOT #8 2019-11-27 09:21

**MOT test number** 547783738149

Result X Failed

**Advice** Rear coil springs corroded

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear exhaust silencer corroded

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #7 2018-11-28 14:53

**MOT test number** 930350493152

**Result** ✓ Passed

MOT #6 2017-11-27 13:13

**MOT test number** 378236421451

**MOT #5** 2016-11-29 08:49

**MOT test number** 190609929803

**Result** ✓ Passed

MOT #4 2016-01-21 10:38

MOT test number 261172028001

**Advice** Both front tires badly worn on inner edges

**Advice** Both front tires worn to legal limit

Advice Both rear tires worn close to legal limit

CarCheck.co.uk page 5/13



MOT #3 2016-01-21 10:27

**MOT test number** 284035201908

Result X Failed

**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Both rear tires worn close to legal limit

Fail Offside Headlamp aim too low (1.8)

**Advice** Both front tires badly worn on inner edges

Fail Nearside Headlamp aim too low (1.8)

Advice Both front tires worn to legal limit

MOT #2 2015-02-02 12:42

**MOT test number** 786693135060

**Result** ✓ Passed

MOT #1 2014-02-19 14:33

MOT test number 866110954028

**Result** ✓ Passed

**Notice** Nsf h/lamp has blue tinge,o/s white.

CarCheck.co.uk page 6/13



#### Tax & MOT check



✓ MOT

Tax expired: 7 March 2024

**Expires:** 19 December 2024

Tax status	Expired at 7 March 2024
Days left	54 days too late
MOT expiry date	19 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NIE NIE NIE
Plate since	
	Moro info

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-09
Last registration	2023-12-07
Complete history	See info



Registration #1	2011-03-09	29 mi
Registration #2	2014-02-19	22.811 mi
Registration #3	2015-02-02	29.142 mi
Registration #4	2016-01-21	37.474 mi
Registration #5	2016-01-21	37.474 mi
Registration #6	2016-11-29	45.612 mi
Registration #7	2017-11-27	55.831 mi
Registration #8	2018-11-28	63.492 mi
Registration #9	2019-11-27	71.121 mi
Registration #10		71.777 es
Registration #11		71.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

page 12/13 CarCheck.co.uk



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2
Engine number 6332630