





### General information

Make	ΤΟΥΟΤΑ
Model	IQ VVT-I IQ
Colour	Red
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

	ē	
Power	67 BHP	0 < 101 A
Max. torque	91 Nm at 4.800 rpm	101 - 120 B
Engine capacity	998 cc	121 - 140 P
Cylinders	3	141 - 165 F
uel type	Petrol	166 - 185
Consumption city	57.7 mpg	186 - 225
onsumption extra urban	72.4 mpg	225+
Consumption combined	65.7 mpg	
CO2 emission	99 g/km	
CO2 label	А	





### Internet history

Entry 1	
Date	2021-06-18
Pictures	3
Listing price	View report









source: autotrader.co.uk



### MOT history

MOT expiry date	2025-04-08
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	24
Total items failed	4

MOT #15	2024-04-09 15:13
MOT test number	761728036097
Result	✓ Passed
Next expiry date	2025-04-08

MOT #14		2023-07-06 08:59
MOT test numbe	er	831878208942
Result		✓ Passed
Advice Oil le	ak, but not excessive (8.4.1 (a) (i))	
Advice Whol	e under car has corrosion	

MOT #13	2022-07-05 14:48
MOT test number	584007013521
Result	✓ Passed
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Whole under body corroded	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #12	2021-07-08 15:19
MOT test number	155915768311
Result	✓ Passed





MOT #11	2020-12-03 12:44
MOT test number	502840148705
Result	✓ Passed
MOT #10	2019-12-14 13:44
MOT test number	740355089960
Result	✓ Passed
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #9	2018-12-15 09:17	
MOT test	number 225489260002	
Result	✓ Passed	
Advice	Under body covers fitted	
Advice	Advice Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))	

MOT #8	2018-12-15 09:17
MOT test number	523083930007
Result	× Failed
Advice Offside Rear Bra	ke pipe corroded, covered in grease or other material corroded (1.1.11 (c))
<b>Pass with rectification</b> (b) (ii))	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4
Advice Under body cove	ers fitted
<b>Pass with rectification</b> (b) (ii))	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #7	2018-01-08 15:52
MOT test number	926051817289
Result	✓ Passed





MOT #6	2016-09-06 10:23
MOT test number	588237482733
Result	✓ Passed
MOT #5	2015-09-14 08:22
MOT test number	298200460511
Result	✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened both front and rear (3.5.1i)

MOT #4		2014-09-01 11:34
MOT test	number	646804044200
Result		✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)
Notice	Horn starting to grate	
Advice	Offside rear brake fluctuating, but not excessively (3.7.B.3)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3	.5.1i)
Advice	Nearside rear brake fluctuating, but not excessively (3.7.B.3)	

MOT #3		2013-08-28 13:27
MOT test	number	165710543293
Result		✓ Passed
Notice	Slight wear and discolouration to both front and rear brake discs	
Notice Offside front tyre is worn		
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





МОТ #2		2013-08-28 13:27
MOT test number		679820443285
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Advice Nearside Front T	yre worn close to the legal limit (4.1.E.1)	
<b>Notice</b> Offside front tyre	e is worn	
Pass with rectification	Offside Headlamp aim too low (1.8)	
Notice Slight wear and	discolouration to both front and rear brake discs	

MOT #1		2012-08-22 13:08
MOT test	number	666695832272
Result		✓ Passed
Notice	Discolouration and slight wear to both front and rear brake discs	
Notice	Front tyres are scrubbing and feathering on outer edges	



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 April 2025	Expires: 8 April 2025
Tax status	Valid until 1 April
Days left	337
MOT expiry date	8 April 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 11.111
Average private trade value	4 10 200





### Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-03
Last registration	2024-04-09
Complete history	<u>See info</u>



Registration #1	2009-09-03	28 mi
Registration #2	2012-08-22	21.098 mi
Registration #3	2013-08-28	26.935 mi
Registration #4	2014-09-01	32.773 mi
Registration #5	2015-09-14	38.411 mi
Registration #6	2016-09-06	44.984 mi
Registration #7	2018-01-08	58.003 mi
Registration #8	2018-12-15	71.113 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		
5		





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg
Additional information	
Fuel tank capacity	32
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	1KR0827053