



Mercedes-Benz

NJZ5244

report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | MERCEDES |
| Model | VITO 111 CDI COMPACT P/V |
| Colour | Blue |
| Year of manufacture | 2008 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-----------------|----------------------|
| Power | 111 BHP |
| Max. torque | 9999 Nm at 9.999 rpm |
| Engine capacity | 2.148 cc |
| Cylinders | 4 |
| Fuel type | Diesel |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-03 |
| Pictures | 35 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-13 |
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 7 |

MOT #72023-08-14 09:10

MOT test number827135899653

Result✓ Passed

Next expiry date2024-08-13

- AdviceRear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))
- AdviceVehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- AdviceCentral Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- AdviceBONNET RELEASE CABLE BROKEN AT HANDLE END
- AdviceOffside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceOffside Front Tyre worn close to legal limit/worn on edge Worn badly on inner edge (5.2.3 (e))
- AdviceRear Coil spring corroded Both (5.3.1 (b) (i))
- AdviceOil leak, but not excessive (8.4.1 (a) (i))

**MOT #6** 2023-08-11 15:13**MOT test number** 652730545841**Result** ✗ Failed**Fail** Drive belt excessively worn (6.1.7 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn badly on inner edge (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Fail** Nearside Windscreen washer not working (3.5 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #5** 2022-07-23 14:14**MOT test number** 414089497648**Result** ✓ Passed**Advice** Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #4** 2022-07-23 13:35**MOT test number** 110253020316**Result** ✗ Failed**Advice** Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Nearside Front Inner Tyre has ply or cords damaged (5.2.3 (d) (ii))**Fail** Nearside Front Inner Tyre has ply or cords damaged (5.2.3 (d) (ii))**Fail** Offside Front Inner Tyre has ply or cords damaged (5.2.3 (d) (ii))**MOT #3** 2021-07-02 15:49**MOT test number** 718479494470**Result** ✓ Passed**MOT #2** 2020-11-07 09:53**MOT test number** 934239058461**Result** ✓ Passed**MOT #1** 2019-09-24 16:19**MOT test number** 854856809467**Result** ✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2008-03-05 |
| Last registration | 2023-08-14 |
| Complete history | See info |



| | | |
|-----------------|------------|------------|
| Registration #1 | 2008-03-05 | 14 mi |
| Registration #2 | 2019-09-24 | 116.110 mi |
| Registration #3 | 2020-11-07 | 119.112 mi |
| Registration #4 | 2021-07-02 | 120.930 mi |
| Registration #5 | 2023-08-14 | 121.277 mi |
| Registration #6 | 2023-08-14 | 121.277 mi |
| Registration #7 | 2023-08-14 | 121.277 mi |
| Registration #8 | 2023-08-14 | 121.277 mi |
| Registration #9 | 2023-08-14 | 121.277 mi |

More info >



Safety ratings

NCAP rating

★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1906 mm |
| Height | 1902 mm |
| Length | 4748 mm |
| Kerb weight | 1885 kg |
| Max. allowed weight | 2770 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 75 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | 64698051605488 |