





report date: 2024-03-29

### General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	Black
Year of manufacture	2012
Top speed	99 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg
CO2 emission	180 g/km
CO2 label	1



CarCheck.co.uk page 1/9



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2023-07-23
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	3
Total items failed	9

MOT #8	2022-07-24 13:24
MOT test number	247241915872
Result	<b>✓</b> Passed
Next expiry date	2023-07-23

MOT #7		2020-02-25 14:13
MOT test	number	550272913741
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #6	2018-09-12 10:33
MOT test number	775790276967
Result	✓ Passed
MOT #5	2017-09-13 14:19
MOT test number	315711112422
Result	✓ Passed

CarCheck.co.uk page 2/9



report date: 2024-03-29

**MOT #4** 2016-07-20 14:29

**MOT test number** 272887364098

MOT #3 2016-07-20 14:29

MOT test number 545199052433

Result X Failed

**Pass with rectification** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**Pass with rectification** Offside Headlamp not working on main beam (1.7.5a)

**Pass with rectification** Front position lamp(s) not working both (1.1.A.3b)

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

MOT #2 2015-09-18 12:38

MOT test number 824858666092

**Result** ✓ Passed

MOT #1 2015-09-18 12:38

**MOT test number** 911993288783

Result × Failed

**Pass with rectification** Front position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance both (1.1.A.3d)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 3/9



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 4/9



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 5/9



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
***************************************	
***************************************	
manus .	
***************************************	
***************************************	
	More info >
Plate changes	
Con in this chool of this DENALUET had different course or glates	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 6/9



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 7/9



CE62VGD report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2012-09-28
Last registration	2022-07-24
Complete history	See info



Registration #1	2012-09-28	16 mi
Registration #2	2015-09-18	80.814 mi
Registration #3	2015-09-18	80.814 mi
Registration #4	2016-07-20	99.632 mi
Registration #5	2016-07-20	99.632 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 8/9



CE62VGD report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

D: 1000	ensior	~ ~ C		ьь
		15 ~	W AIR	

Width	1904 mm
Height	1944 mm
Length	4782 mm
Kerb weight	1710 kg
Max. allowed weight	2790 kg

## Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C033528

CarCheck.co.uk page 9/9